



OVERVIEW

---

<b>DATE ISSUED:</b>	<i>Feb 9, 2021</i>	<b>TRACKING NUMBER:</b>	<b>4134815</b>
<b>ISSUED BY:</b>	AirPrime Product Management		
<b>PRODUCTS AFFECTED:</b>	<i>Linux SLQS and Android RIL (for 9x50, 9x30, 9x15, 9x07 based products)</i>		
<b>BULLETIN:</b>	<i>EOL Linux SLQS &amp; Android RIL</i>		
<b>URGENCY:</b>	Normal		
<b>FOR DISTRIBUTION TO:</b>	<i>All customers and their partners using the products</i>		

**Summary**

---

Sierra Wireless is hereby announcing the EOL of all legacy Linux SDK, Android RIL, and Gobi Drivers for Qualcomm MDM9x50, MDM9x30, MDM9x15, and MDM9x07 based products.

Moving forward, customers should integrate Sierra Wireless modules using Mobile Broadband Packages for Linux (MBPL) and Mobile Broadband Packages for Android (MBPA).

**Details**

---

To streamline the SW release cycle and improve support, Sierra Wireless is hereby announcing the EOL of all Linux SDK, Android RIL, and Gobi Drivers for Qualcomm MDM9x50, MDM9x30, MDM9x15, and MDM9x07 based products. All support for existing Linux SDK, Android RIL, and Gobi drivers will cease immediately. No future releases are planned.

**Last Linux Release:** Linux SLQ04.00.27

**Last Android Release:** Android RIL 10.0.7.0

Customers can continue to use Linux SDK and Android RIL, however, no future releases and fixes are planned.

Customers are recommended to migrate and adopt Mobile Broadband Packages for Linux (MBPL) and Mobile Broadband Package for Android (MBPA) for their existing and new platforms. SW Development and Integration guides are available to help with this transition.

**Timeline**

---

Immediate EOL of existing Linux SDK, Android RIL, and Gobi Drivers for Qualcomm MDM9x50, MDM9x30, MDM9x15, and MDM9x07 based products. No features, fixes, patches will be provided.

MBPL (Linux) R18/19 scheduled for Q1 2021 will include support and documentation updates for all existing MOL products.

MBPA (Android) evaluation releases for MOL products targeted for mid Q2/2021.

**More information**

---

For more information please contact your Sierra Wireless sales/technical support person.

SKU#	Product Model	Description
1103408	EM7430	EM7430,GENERIC,GENERIC/DOCOMO/
1102475	EM7430	EM7430,GENERIC,GENERIC\\TELSTRA
1103582	EM7455	EM7455,GENERIC,GENERIC/AT&T/SP
1102623	EM7455	EM7455,GENERIC,GENERIC/AT&T/VE
1104268	EM7511	EM7511,GENERIC,VERIZON/AT&T/GE
1103520	EM7565	EM7565 ,GENERIC,GENERIC,01.00.
1103520	EM7565	EM7565,GENERIC,GENERIC,01.00.0
1103520	EM7565	EM7565,GENERIC,GENERIC,01.07.0
1104628	EM7690	EM7690,GENERIC,,,,,,,,SWIR IMEI,
1104629	EM9191	EM9191,GENERIC,GENERIC,01.07.0
1103730	MC7430	MC7430,GENERIC,Generic/Docomo/
1102477	MC7430	MC7430,GENERIC,GENERIC\\TELSTRA
1102476	MC7455	MC7455,GENERIC,GENERIC/AT&T/SP
1103578	MC7455	MC7455,GENERIC,GENERIC/AT&T/SP
1102476	MC7455	MC7455,GENERIC,GENERIC/AT&T/VE
1103114	WP7502	WP7502,GENERIC,GENERIC,RELEASE
1103669	WP7504	WP7504,QUALIFIED,GENERIC,R14,L
1103576	WP7504	WP7504,QUALIFIED,SPRINT,RELEAS
1103576	WP7504	WP7504,QUALIFIED,SPRINT/AT&T/G
1104245	WP7601	WP7601-1,GENERIC,VERIZON,R10.1
1104246	WP7601	WP7601-1,GENERIC,VERIZON,R10.2
1103728	WP7601	WP7601-1,GENERIC,VERIZON,R7.0.
1103728	WP7601	WP7601-1,QUALIFIED,VERIZON,R5.
1104248	WP7603	WP7603,GENERIC,AT&T/GENERIC/SI
1104250	WP7603	WP7603-1,GENERIC,AT&T/GENERIC/
1103511	WP7607	WP7607,GENERIC,GENERIC,R8,LEGA
1104192	WP7607	WP7607,GENERIC,GENERIC/SIERRA,
1103529	WP7607	WP7607-1,GENERIC,GENERIC,R7,LE
1104193	WP7607	WP7607-1,GENERIC,GENERIC/SIERR
1104196	WP7609	WP7609,GENERIC,GENERIC/SIERRA,
1104125	WP7610	WP7610,GENERIC,AT&T/GENERIC/VE
1103530	WP7702	WP7702,GENERIC,GENERIC,R8,LEGA
1103530	WP7702	WP7702,GENERIC,GENERIC,R9,LEGA
1104214	WP7702	WP7702,GENERIC,GENERIC/AT&T/SI
1104214	WP7702	WP7702,GENERIC,GENERIC/AT&T/VE
1103113	WP8548	WP8548,Generic,Generic,RELEASE
1103552	WP8548	WP8548,QUALIFIED,GENERIC,RELEA
1104595	RC7611	RC7611,GENERIC,GENERIC/AT&T/VE
1104617	RC7611	RC7611-1,GENERIC,GENERIC/AT&T/