

PRODUCT CHANGE NOTIFICATION

PCN#: INDUSTRIALNET COPPER

YYYYMMDD-X

ISSUE DATE: _____

IMPACTED REGIONS: NA EMEA LATAM AP

REASON FOR CHANGE: DISCONTINUATION
 OTHER

DESCRIPTION OF CHANGE: (Not Required for discontinuation)

The following parts have had a change made to the Panduit part number. The new parts have no changes in standard construction, SF/UTP TPE cables. The new parts actually have improved performance and characteristics such as 600V AWM rating. The three parts starting with ICY have had a cable color change from black to teal.
 Photos/Drawing (where applicable)

IMPACTED PART NUMBERS AND REPLACEMENT PART NUMBERS: (where applicable)

[Reference Page 2 / Linked PDF](#)

DATES: DISCONTINUATION AND NEW PRODUCT AVAILABILITY:

SCHEDULE FOR CHANGE	Year (YYYY)	Month (MM)	Day (DD)
New product sample availability date	2019	8	5
Old product discontinuation date*	2019	7	22

***Important:** After old product discontinuation date, the affected part numbers listed above will continue to be available for sale as long as supplies last. Product may be returned up to 60 days after the product continuation date.

IMPACTED PART NUMBER(s)	REPLACEMENT PART NUMBER(s)
ICD15T2NTL0.5M	ICD15T1NTL0.5M
ICD15T2NTL10M	ICD15T1NTL10M
ICD15T2NTL15M	ICD15T1NTL15M
ICD15T2NTL1M	ICD15T1NTL1M
ICD15T2NTL20M	ICD15T1NTL20M
ICD15T2NTL2M	ICD15T1NTL2M
ICD15T2NTL3M	ICD15T1NTL3M
ICD15T2NTL5M	ICD15T1NTL5M
ICD25T2NTL0.5M	ICD25T1NTL0.5M
ICD25T2NTL10M	ICD25T1NTL10M
ICD25T2NTL15M	ICD25T1NTL15M
ICD25T2NTL1M	ICD25T1NTL1M
ICD25T2NTL20M	ICD25T1NTL20M
ICD25T2NTL2M	ICD25T1NTL2M
ICD25T2NTL3M	ICD25T1NTL3M
ICD25T2NTL5M	ICD25T1NTL5M
ICD35T2NTL0.5M	ICD35T1NTL0.5M
ICD35T2NTL10M	ICD35T1NTL10M
ICD35T2NTL15M	ICD35T1NTL15M
ICD35T2NTL1M	ICD35T1NTL1M
ICD35T2NTL20M	ICD35T1NTL20M
ICD35T2NTL2M	ICD35T1NTL2M
ICD35T2NTL3M	ICD35T1NTL3M
ICD35T2NTL5M	ICD35T1NTL5M
ICX44T1NBL1M	ICX44T1NTL1M
ICX44T1NBL2M	ICX44T1NTL2M
ICX45T1NBL0.5M	ICX45T1NTL0.5M