


Product Advisory

Issue Date: March 6, 2019

Change Type:

Broadcom DCSG adapter kit boxes currently include a black label on the edge of the box that includes adapter features and the product barcode. This advisory notifies customers that this black label is being removed and replaced with a barcode label only.



Parts Affected:

The following kit packages are affected:

MPN	Description	MPN	Description
05-50028-00	MegaRAID 9365-28i SGL	05-50047-00	HBA 9405W-16i
05-50011-02	MegaRAID SAS 9460-8i SGL	05-50044-00	HBA 9405W-16e
05-50011-00	MegaRAID SAS 9460-16i SGL	05-50031-02	HBA 9400-8i8e
05-50031-00	MegaRAID SAS 9480-8i8e SGL	05-50008-00	SAS 9400-16i
05-50008-02	MegaRAID SAS 9440-8i SGL	05-50008-01	SAS 9400-8i
05-50022-00	MegaRAID SAS 9361-24i SGL	05-50013-00	SAS 9400-16e
05-25716-00	MegaRAID SAS 9380-8i8e SGL	05-50013-01	SAS 9400-8e
05-25708-00	MegaRAID SAS 9361-16i SGL	05-25699-00	SAS 9305-24i
05-25420-17	MegaRAID SAS 9361-8i (2G) SGL	05-25703-00	SAS 9305-16i
05-26105-00	MegaRAID SAS 9341-4i SGL	05-25704-00	SAS 9305-16e
05-26106-00	MegaRAID SAS 9341-8i SGL	05-25688-00	SAS 9302-16e SGL
05-25420-10	MegaRAID SAS 9361-4i SGL	05-25600-00	SAS 9300-16i SGL



05-25420-08	MegaRAID SAS 9361-8i SGL	H5-25460-00	SAS 9300-8e SGL
05-25528-04	MegaRAID SAS 9380-8e SGL	H5-25573-00	SAS 9300-8i SGL
05-25190-02	MegaRAID SAS 9380-4i4e SGL	H5-25473-00	SAS 9300-4i SGL
H5-25520-00	SAS 9300-16e SGL	H5-25515-00	SAS 9300-4i4e SGL

Description and Extent of Change:

The black feature label on the edge of the adapter kit boxes is being removed. It will be replaced with a white barcode label including the adapter name. This label will be placed on the edge of the box in roughly the same location as the existing bar code on the black label. An example of the label is shown here:



Effect of Change on Fit, Form, Function, Quality, or Reliability:

There is no impact to form, fit, or function, quality or reliability.

Effective Date of Change:

Product shipments using this change will begin on or around March 15, 2019 but initiation of the change may be spread over approximately 6 months. Timing of shipment of the changed part will vary by part number depending on customer demand and inventory levels.

Please contact your Broadcom Inc. field sales engineer or Contact Center (<http://www.broadcom.com/contact/>) for any questions or support requirements.