


1 Products affected

Product hierarchy no. *				Part no.	SBU	Type / Description	Customer part no.
SBU	PG	PGU	Type				
80	080	001	0000006170	FMBD-B92D-8012	EMC	FMBD NEO FILTER 3PH+N	
80	080	001	0000006170	FMBD-B92E-J212	EMC	FMBD NEO FILTER 3PH+N	
80	080	001	0000006179	FMBC-A91G-J01x	EMC	FMBC NEO FILTER 3PH	
80	080	001	0000006179	FMBC-A91G-J31x	EMC	FMBC NEO FILTER 3PH	
80	080	001	0000006195	FMAC-091G-H110	EMC	FMAC ECO FILTER 3PH	
80	080	001	0000006195	FMAC-091G-H210	EMC	FMAC ECO FILTER 3PH	
80	080	006	0000006002	FMER-Gy2R-J017	EMC	FMER SOL FILTER DC	

*SBU (2-digit) / PG (3-digit) / PGU (3-digit) / Type (10-digit)
x = 0 or 2 ; y = 6 or 9

2 Type of change



3 Detailed description of change

Replacement of the EUROCLAMP terminal blocks MPT 5018 (50mm², with Torx screws) with the PHOENIX terminal blocks HDFK 50 (50mm², with hexagon socket screws).

4 Reason of change

Quality improvement of the clamp terminals.

5 Released date

07.07.2011 (COORDINA 0611)

FMBC NEO, FMBD NEO, FMAC ECO, FMER SOL					0118.2073	
Creation date:	Created by:	Release date:	Released by:	Notification No.	Index	Page
26.08.2011 11:43:51	BLU	16.09.2011	BLU	22331	-	1 von 2

6 Impact of change and recommended action

Form: No influence
Fit: No influence
Function: No influence
Production Site: No influence

7 Reference Documents / Attachments

Kind of document	Document number	Remarks

FMBC NEO, FMBD NEO, FMAC ECO, FMER SOL					0118.2073	
Creation date:	Created by:	Release date:	Released by:	Notification No.	Index	Page
26.08.2011 11:43:51	BLU	16.09.2011	BLU	22331	-	2 von 2