

PCN Number:	20180109001	PCN Date:	January 15, 2018
Title:	Datasheet for TPS25942A, TPS25942L, TPS25944A, TPS25944L		
Customer Contact:	PCN Manager	Dept:	Quality Services
Change Type:			
<input type="checkbox"/>	Assembly Site	<input type="checkbox"/>	Design
<input type="checkbox"/>	Assembly Process	<input checked="" type="checkbox"/>	Data Sheet
<input type="checkbox"/>	Assembly Materials	<input type="checkbox"/>	Part number change
<input type="checkbox"/>	Mechanical Specification	<input type="checkbox"/>	Test Site
<input type="checkbox"/>	Packing/Shipping/Labeling	<input type="checkbox"/>	Test Process
<input type="checkbox"/>		<input type="checkbox"/>	Wafer Bump Site
<input type="checkbox"/>		<input type="checkbox"/>	Wafer Bump Material
<input type="checkbox"/>		<input type="checkbox"/>	Wafer Bump Process
<input type="checkbox"/>		<input type="checkbox"/>	Wafer Fab Site
<input type="checkbox"/>		<input type="checkbox"/>	Wafer Fab Materials
<input type="checkbox"/>		<input type="checkbox"/>	Wafer Fab Process

Notification Details

Description of Change:

Texas Instruments Incorporated is announcing an information only notification. The product datasheet(s) is being updated as summarized below. The following change history provides further details.



TPS25942A, TPS25942L, TPS25944A, TPS25944L
SLVSCE9D – JUNE 2014 – REVISED OCTOBER 2017

Changes from Revision C (January 2017) to Revision D

Page

- | | |
|--|----|
| • Added section 9.3.5 Reverse Current Protection to <i>Feature Description</i> | 25 |
|--|----|

The datasheet number will be changing.

Device Family	Change From:	Change To:
TPS25942A, TPS25942L, TPS25944A, TPS25944L	SLVSCE9C	SLVSCE9D

These changes may be reviewed at the datasheet links provided.

<http://www.ti.com/product/TPS25944A>

Reason for Change:

To accurately reflect device usage in specific application use cases.

Anticipated impact on Fit, Form, Function, Quality or Reliability (positive / negative):

No anticipated impact. This is a recommendation change to application circuit only. There are no changes to the actual device.

Changes to product identification resulting from this PCN:

None.

Product Affected:

TPS25942ARVCR	TPS25942LRVCR	TPS25944ARVCR	TPS25944LRVCR
TPS25942ARVCT	TPS25942LRVCT	TPS25944ARVCT	TPS25944LRVCT

For questions regarding this notice, e-mails can be sent to the regional contacts shown below or your local Field Sales Representative.

Location	E-Mail
USA	PCNAmericasContact@list.ti.com
Europe	PCNEuropeContact@list.ti.com
Asia Pacific	PCNAsiaContact@list.ti.com
Japan	PCNJapanContact@list.ti.com