

EFFECTIVE IMMEDIATELY

Date 06/21/2022

Dear Fluke Distributor:

The following distribution Product is being phased out effective immediately. This letter is your notification of our product change.

PLEASE INFORM ALL RELEVANT PERSONNEL WITHIN YOUR ORGANIZATION.

Product Family	Obsolete Item Number	Obsolete Model	Suggested Replacement Item	Suggested Replacement Model	
POM	3387997	73057,TNC STRAIGHT PLUG, 50 OHM, CRIMP TYPE, RG59, 62	3387960 & 3387985	May be replaced by model 73054 and 73056	
POM	3388166	73063-BB-24,MMCX PLUG TO MMCX PLUG, RG316/U, 24 INCH	No direct replacement	NA	
POM	3388298	73066-BB-36,MMCX RIGHT-ANGLE PLUG TO SMA BULKHEAD JACK, RG316/U, 36 INCH	3388306	May be replaced by model 73066-BB-48	
POM	3388338	73067-BB-36,MCX PLUG TO MCX PLUG, RG316/U, 36 INCH	No direct replacement	NA	
POM	3388389	73068-BB-6,MCX RIGHT-ANGLE PLUG TO MCX RIGHT-ANGLE PLUG, RG316/U, 6 INCH	No direct replacement	NA	
POM	3388470	73070-BB-48,SMA PLUG TO SMA BULKHEAD JACK, RG316/U, 48 INCH	3388535	may be replaced by model 73070-C-60	
POM	3388496	73070-C-12,SMA PLUG TO SMA BULKHEAD JACK, RG58C/U, 12 INCH	3388535	may be replaced by model 73070-C-60	
POM	3388501	73070-C-24,SMA PLUG TO SMA BULKHEAD	3388535	may be replaced by	

		JACK, RG58C/U, 24 INCH		model 73070-C-60	
POM	3388573	73071-BB-48,SMA RIGHT-ANGLE PLUG TO SMA BULKHEAD JACK, RG316/U, 48 INCH	3388547	may be replaced by model 73071-BB-12	
POM	3388586	73071-BB-60,SMA RIGHT-ANGLE PLUG TO SMA BULKHEAD JACK, RG316/U, 60 INCH	3388547	may be replaced by model 73071-BB-12	
POM	3388599	73071-X-12,SMA RIGHT-ANGLE PLUG TO SMA BULKHEAD JACK, RG142B/U, 12 INCH	3388607	may be replaced by model 73071-X-24	
POM	3388629	73071-X-48,SMA RIGHT-ANGLE PLUG TO SMA BULKHEAD JACK, RG142B/U, 48 INCH	3388607	may be replaced by model 73071-X-24	
POM	3388634	73071-X-60,SMA RIGHT-ANGLE PLUG TO SMA BULKHEAD JACK, RG142B/U, 60 INCH	3388607	may be replaced by model 73071-X-24	
POM	3388690	73072-VV-24,SMB JACK TO SMB JACK, RG179/U, 75 OHM, 24 INCH	3388708	may be replaced by model 73072-VV-36	
POM	3388713	73072-VV-48,SMB JACK TO SMB JACK, RG179/U, 75 OHM, 48 INCH	3388708	may be replaced by model 73072-VV-36	
POM	3388724	73072-VV-60,SMB JACK TO SMB JACK, RG179/U, 75 OHM, 60 INCH	3388708	may be replaced by model 73072-VV-36	
POM	3388749	73073-BB-12,SMB RIGHT-ANGLE JACK TO SMB RIGHT-ANGLE JACK, RG316/U, 12 INCH	3388760	may be replaced by model 73073-BB-36	
POM	3388772	73073-BB-48,SMB RIGHT-ANGLE JACK TO SMB RIGHT-ANGLE JACK, RG316/U, 48 INCH	3388760	may be replaced by model 73073-BB-36	

POM	3388797	73075-UU-12,MCX PLUG TO MCX PLUG, RG178/U, 12 INCH	No direct replacement	NA	
POM	3388805	73075-UU-24,MCX PLUG TO MCX PLUG, RG178/U, 24 INCH	No direct replacement	NA	
POM	3388822	73075-UU-48,MCX PLUG TO MCX PLUG, RG178/U, 48 INCH	No direct replacement	NA	
POM	3388846	73075-VV-24,MCX PLUG TO MCX PLUG, RG179/U, 75 OHM, 24 INCH	3388854	may be replaced by model 73075-VV-36	
POM	3389062	73083-X-24,SMA QUICK-CONNECT PLUG TO SMA QUICK-CONNECT PLUG, RG142B/U, 24 INCH	3389037	may be replaced by model 73083-BB-48	
POM	3389070	73083-X-36,SMA QUICK-CONNECT PLUG TO SMA QUICK-CONNECT PLUG, RG142B/U, 36 INCH	3389037	may be replaced by model 73083-BB-48	
POM	3389081	73083-X-48,SMA QUICK-CONNECT PLUG TO SMA QUICK-CONNECT PLUG, RG142B/U, 48 INCH	3389037	may be replaced by model 73083-BB-48	
POM	3389096	73083-X-60,SMA QUICK-CONNECT PLUG TO SMA QUICK-CONNECT PLUG, RG142B/U, 60 INCH	3389043	may be replaced by model 73083-BB-60	

Should you have any questions regarding this notice, please contact your Fluke Sales Manager.

Kind regards,
Zak Bollenbacher
Sr. Director of Commercial Strategy