

PRODUCT CHANGE NOTIFICATION

Product Category COPPER - CABLE - 1G

20200803

Product Group COPPER CABLE

ISSUE DATE: 20200803

IMPACTED REGIONS: NA EMEA LATAM AP

REASON FOR CHANGE: DISCONTINUATION
 OTHER

DESCRIPTION OF CHANGE: (Required)

Parts are being discontinued in order to streamline the product offering

Photos/Drawing (where applicable)

IMPACTED PART NUMBERS AND REPLACEMENT PART NUMBERS: (where applicable)

[Reference Page 2 / Linked PDF](#)

DATES: DISCONTINUATION AND NEW PRODUCT AVAILABILITY:

SCHEDULE FOR CHANGE	Year (YYYY)	Month (MM)	Day (DD)
New product sample availability date	2020	8	3
Old product discontinuation date*	2020	11	3

***Important:** A return material authorization (RMA) may be obtained for these affected part numbers and they may be returned up to 60 days after the product discontinuation announcement date if purchased within the last 18 months and subject to the return policy requirements outlined in Panduit's 1/1/19 Authorized Distributor Policy. Please contact your local Panduit Customer Experience team if you have any questions.

IMPACTED PART NUMBER(s)	Replacement Type	Replacement Part 1
PUP6004BU-C	Direct Replacement	PUP6004BU-FLP
PUP6004BL-C	Direct Replacement	PUP6004BL-FLP
PUP6004IG-C	Direct Replacement	PUP6004IG-FLP
PUP6004GR-C	Direct Replacement	PUP6004GR-FLP
PUP6004RD-C	Direct Replacement	PUP6004RD-FLP
PUP6004OR-C	Direct Replacement	PUP6004OR-FLP
PUP6004VL-C	Direct Replacement	PUP6004VL-FLP
PUP6004WH-C	Direct Replacement	PUP6004WH-FLP
PUP6004YL-C	Direct Replacement	PUP6004YL-FLP
PUP6004BU-C-S	No Replacement	
PUP6004BL-C-S	No Replacement	
PUP6004IG-C-S	No Replacement	
PUP6004GR-C-S	No Replacement	
PUP6004RD-C-S	No Replacement	
PUP6004OR-C-S	No Replacement	
PUP6004VL-C-S	No Replacement	
PUP6004WH-C-S	No Replacement	
PUP6004YL-C-S	No Replacement	