



Product Change Notification (PCN)

| | | | |
|---|--|-------------|------------------|
| PCN Number | 511073 | Date Issued | October 13, 2021 |
| Reason for Change | Change Supplier | | |
| Change Type Description | This letter is to inform you that Molex is adding a new supplier or the supplier is making a change affecting the part(s) identified in this notice. There will be no negative impact to product performance as a result of this change. | | |
| Reason for Short Notice | Special Request | | |
| Assessment of Change | Test report/Specification Test Report | | |
| Internal Molex Qualification Date | October 13, 2021 | | |
| Sample Availability Date (Changed Part) | October 13, 2021 | | |
| Planned Implementation Date | November 17, 2021 | | |
| Method of Identifying Change | Special marking on the product or packaging | | |

RELEASED



Before Change

| | Raw Material | Main Objective Products |
|-------------|--------------|--|
| Current | PC UL94V-0 | 54017, 54018, 54280, 54599, 55100, 500654, 500655, 53989, 53990, 54181, 54182 series |
| Alternative | PC UL94V-0 | |

- The severe winter storm that had widespread impacts across the United States, Northern Mexico, and parts of Canada from February 13 to 17, 2021 has caused a global shortage for various grades of resin. This extraordinary event, in conjunction with an already constrained market, has caused immediate and severe disruption in the industry.
- Due to these supply constraints, Molex identified an internal shortage of resin supply with would create a challenge to fulfill all orders. Therefore, we identified an alternative sourcing for the product families listed above. After applying of this change, Molex products listed above will be manufactured by one of them - the current supplier's material or the alternative supplier's one by the resin material supply situation.
- We apologize for the inconvenience, but in view of the urgency of this matter, if there is no particular reply to the change notified by this PCN, it will be considered that the change have been approved and will be implemented with the above Planned implementation Date.
- Part number Impacted: See the attached impacted parts list. Customer part list may include different series of items other than above which use Molex Japan products as component part may manufacture in other Molex entities.

After Change

- The alternative supplier operates under ISO9001 certified quality management system.
- Molex material scientists conducted comprehensive equivalency analysis comparing properties of resins between the original supplier and alternative supplier. This is being followed by Molex internal qualification testing which shall ensure that finished products meet relevant product specifications before delivery.
- Though it may see a slight shade difference, there is no other expected change regarding form, fit and function.

| PN | Description | Current | Alternative |
|------------|---------------------------|---|---|
| 54595-1005 | 2.0 I/O Plug Mold Cover B |  |  |

- Identification:
For the first 6 months of the production start by the alternative material, we will add "M" at the end of Traceability number (see the picture right) of the label to identify products made from alternative materials.





Product Change Notification (PCN)

You may address any technical inquiries regarding this PCN by sending E-mail to pcn_coordinator@molex.com or your Local Sales Engineer.

Note: While responding, please retain "**PCN Notification:511073**" in the e-mail Subject line for faster response.

RELEASED

Molex, LLC
2222 Wellington Court
Lisle, IL 60532
TEL: 630-969-4747
www.molex.com

| PCN # | Molex Part # |
|--------|--------------|
| 511073 | 540170615 |
| 511073 | 540180605 |
| 511073 | 545991019 |
| 511073 | 551000670 |
| 511073 | 551000680 |
| 511073 | 5006540609 |

Affected Parts:

| |
|------------|
| 54280-0609 |
| 54599-1019 |
| 55100-0670 |