



CUSTOMER ADVISORY

Titanium Ti60 & Ti35 Boundary-Scan Test Support

| | |
|-------------------------|---|
| Advisory Details | <p>The Ti60 and Ti35 boundary-scan test can fail inconsistently for some parts. Efinix has implemented a test to screen the parts that caused the inconsistent failures.</p> <p>All parts marked with date code “2228” or later are screened with a new test and will give a consistent boundary-scan test result.</p> <p>If the customer plans to use the boundary scan test, the customer must use parts marked with date code “2228 or later.</p> <p>If the customer plans to use the boundary scan test with parts before the date code “2228”, the customer should contact Efinix using the contact information below for further disposition.</p> |
| Parts Affected | <p>All Ti60 & Ti35 devices and variants</p> <ul style="list-style-type: none"> • Ti60F225XX • Ti35F225XX • Ti60F100S3F2XX • Ti35F100S3F2XX <p>XX = All speed grades</p> |
| Contact: | <p>For more information, please contact your local Sales or FAE or contact us online at https://www.efinixinc.com/company-contact-us.html .</p> |