



**PCN: V16-009-32002150-0A**

## Product Change Notice

Issue Date: 21 Nov 2016

### Change Type:

Qualify additional Testing and Sawing site for Automotive's LED

### Parts Affected:

ACPL-312T	ACPL-K30T	ACPL-M43T	ACPL-782T
ACPL-31JT	ACPL-K33T	ACPL-M46T	ACPL-C797T
ACPL-32JT	ACPL-K34T	ACPL-M49T	ACPL-C87AT
ACPL-33JT	ACPL-K43T	ACPL-M61T	ACPL-C87BT
ACPL-344JT	ACPL-K44T	ACPL-M71T	
ACPL-34JT	ACPL-K49T	ACPL-M72T	
ACPL-36JT	ACPL-K71T	ACFL-5211T	
ACPL-38JT	ACPL-K72T	ACFL-5212T	
ACPL-36JV	ACPL-K74T	ACFL-6211T	
	ACPL-K75T	ACFL-6212T	

All associated options and specials will also be affected.

### Description and Extent of Change:

Existing site for Testing and Sawing of Industrial's LEDs will be expanded to include Automotive's LED

### Reasons for Change:

Capacity expansion

### Effect of Change on Fit, Form, Function, Quality, or Reliability:

The product will be tested according to the datasheet specifications (No change). There is no change to fit, form, function of the product due to the above-mentioned changes. Appropriate qualification has been performed on the product to ensure normal parametric distribution, consistent electrical performance, and reliability.

### Effective Date of Change:

Implementation of above-mentioned changes will be effective from product date code **1726** (yyww) inclusive, product marking **1726** (yyww).

**Qualification Data:**

Qualification data is available. These changes will be reviewed and approved by Broadcom Limited engineers and managers per Broadcom Limited change notification procedure.

Please contact your Broadcom Limited field sales engineer or Contact Center (<http://www.broadcom.com/contact/>) for any questions or support requirements. Please return any response as soon as possible and not to exceeding 30 days.

---

These changes have been reviewed and approved by Broadcom Limited engineers and managers per Broadcom Limited procedure: Change Control and Customer Notification, A-5962-6052-80.

Please contact your Broadcom Limited field sales engineer or Contact Center (<http://www.broadcom.com/contact/>) for any questions or support requirements. Please return any response as soon as possible, but not to exceed 30 days.