PRODUCT CHANGE NOTIFICATION

Product Category RACKS **20200130**

Product Group ROAR

ISSUE DATE: 1/17/2020

IMPACTED REGIONS: ☑ NA ☑ EMEA ☑ LATAM ☑ AP

REASON FOR CHANGE: ☐ DISCONTINUATION ☑ OTHER

DESCRIPTION OF CHANGE: (Required)

Product Change: Added additional pems and second piece of DIN rail to rear of bracket. Removed knockouts. Added end caps to the DIN rails.

IMPACTED PART NUMBER(s)	**Replacement Part**
IABDIN4	

IMPACTED PART NUMBERS AND REPLACEMENT PART NUMBERS: (where applicable)

DATES: DISCONTINUATION AND NEW PRODUCT AVAILABILITY:

SCHEDULE FOR CHANGE	Year (YYYY)	Month (MM)	Day (DD)
New product sample availability date	2020	1	20
Old product discontinuation date*	2020	1	20

***Important:** A return material authorization (RMA) may be obtained for these affected part numbers and they may be returned up to 60 days after the product discontinuation announcement date if purchased within the last 18 months and subject to the return policy requirements outlined in Panduit's 1/1/19 Authorized Distributor Policy. Please contact your local Panduit Customer Experience team if you have any questions.