PRODUCT CHANGE NOTIFICATION (PCN)

| **PCN#**	WPC-180306-001	**Issuing Date**	March 06th, 2018

PRODUCT(S) AFFECTED :

Attachment: ☐Yes   ■No

Product Name	Description	Supplying Schedule
W5500 Ethernet Shield	Revision: Rev1.0 → Rev1.1	March 06th, 2018

Description of Changes

In Rev 1.0, GND pin of "RESET" button(S1) was floating.

This change in Rev1.1 will solve the floating problem. (Connect to GND with adding VIA.)

Refer to below picture.

W5500 Ethernet shield Rev1.0	W5500 Ethernet shield Rev1.1

DISTRIBUTORS NOTIFICATIOON :

DISTRIBUTOR ACKNOWLEDGEMENT : Distributors may use this form to acknowledge receipt of this notification. Please fill in the below form and return it to us.

Distributor		Date	
Name		Title	
E-mail			
Comments			