



Product/Process Change Notifications



PCN - 14 073-R.2

Release Date: October 17 2014

Product Name:	SFP+ BOARD CONN ASSY		
	SFP+ BOARD CONN ASSY		
Product Manager:	Lynn Zhou		
Subject:	Notification of Change with Immediate Effectivity		
Distribution	General		
Type of Change:	Design Change		
Change Description:	<div style="display: flex; justify-content: space-around;"> <div style="text-align: center;"> <p><small>Before Change</small></p>  <p style="background-color: yellow; font-size: small;">There are four pin numbers 1,10,11,20 marked on the SFP+ connector housing</p> </div> <div style="text-align: center;"> <p><small>After Change</small></p>  <p style="background-color: yellow; font-size: small;">pin number markings 10,11,20 are removed. Larger pin number 1 moved to the left of the housing is the only available marking .</p> </div> </div> <p>1)Correct the wrong spelling specification numbers in GS-20-0385. Product Specification : GS-12-1411 (before change)→ GS-12-1141 (after change); Package Specification : GS-14-1399(before change)→ GS-14-2372(after change). 2)Correct the wrong spelling specification numbers in customer drawing. Package Specification : GS-14-1399(before change)→ GS-14-2372(after change). 3)Add UL 94V-0 in customer drawing: HOUSING:HIGH PERFORMANCE RESINS,BLACK(before change)→HOUSING:HIGH PERFORMANCE RESINS,BLACK UL 94V-0 (after change)</p>		
Reason for Change:	Correct the wrong pin location mark on the housing and spelling errors.FCI decides immediately make effective this PCN in to avoid any misunderstanding on the pin location at customer side <i>By R.2 , affected part number has been corrected to 10122424-101LF instead of 10122424-101L</i>		
Affected Parts:	10122424-101LF/10122424-901LF		
Effective Date of Change:	October 17, 2014		
Last Time Buy Date:	NA		
Last Disty Return Date:	NA		
Last Time Shipment Date	NA		
Datasheet Attached?	No		
Qual/Test Data Attached?	No		
Samples Availability Date:	October	17	2014
Available Alternatives?	N/A		
Questions?	<i>Contact your local FCI Representative, or Product Manager</i>		
	<i>Lynn Zhou/ Product Manager-Dongguan site</i>		
	<i>86-769-88682108 Ext: 603 / ZhouLy@fci.com</i>		

Note:

Customer shall intimate the product Manager any Concern regarding the PCN within 3 weeks of the release date.
 PCN is considered approved by the customer if no communication is received within 3 weeks