



Product Change Notification

TE Connectivity

Product Change Notification: P-20-018900

PCN Date: 08-APR-20

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:

Notification of Lead Time changes due to Corona Virus impact on tubing products.

Description of Changes

This is a notification informing TE Connectivity customers that the Lead Times for tubing products are changing due the impact of Covid 19 Virus on Production.

Other attachments:

[PCN - Changes to Tubing lead times](#)

[Appliance Tubing - adjustment lead times 1](#)

[Appliance Tubing - adjustment lead times 2](#)

Reason for Changes:

Document clarification. The Trutnov tubing plant remains open and producing as much heat Shrink tubing as it can however due to the closure of borders in the Czech Republic for reasons of Covid 19 virus protection we are not able to staff the factory at the required levels to keep up with required productivity outputs. This reduction has regrettably forced us to increase Lead Times for the tubing products.

Estimated Dates:

Last Order Date (Obsolete Parts Only):	First Date To Ship (Changed Parts Only):
	13-APR-2020

Last Ship Date (Obsolete Parts Only):	Last Date for Mixed Shipments: (Changed Parts Only):
	No Mixed Shipments

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
0534174011	NO			"8-1190407-6", "RT-375-3/64-X-SP"			
085193P003	NO			"9-1190628-5", "ES1000-NO.4-B7-X-STK"			
085193P006	NO			"9-1190628-8", "ES1000-NO.4-B7-X-50MM"			
0893834001	NO			"9-1190655-8", "CGPT-39/13-4-SP"			
130599P003	NO			"6-1190948-1", "ES2000-NO.4-B7-0-75MM"			
130599P006	NO			"6-1190948-4", "ES2000-NO.4-B7-0-STK"			
130599P007	NO			"6-1190948-5", "ES2000-NO.4-B7-0-60MM"			
130599P011	NO			"6-1190948-8", "ES2000-NO.4-B7-0-50MM"			
2886154007	NO			"8-1192188-3", "CGAT-24/8-0-SP"			
3075774001	NO			"6-1192329-0", "HTAT-16/4-0-SP"			
3133334001	NO			"2-1192370-4", "CGPT-24/8-9-SP"			
3137794006	NO			"4-1192373-4", "RT-375-1-X-SP"			
349256-000	NO			"4-1200721-0", "VERSAFIT-1/8-KT2-REFILL"			
4951524017	NO			"7-1193702-5", "ATUM-32/8-0-SP"			
5052934106	NO			"2-1193826-7", "RNF-100-1/16-WH-SP"			
5053044177	NO			"RNF-100-3/16-BK-SP", "RNF-100-3/16-0", "1832174-1"			
5053064027	NO			"9-1193841-4", "RNF-100-3/16-4-SP"			
5053064084	NO			"9-1193841-6", "RNF-100-3/16-YO-SP"			
5053104060	NO						

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
				"4-1193848-9", "RNF-100-1/4-RD-SP", "RNF-100-1/4-2"			
5053274018	NO			"4-1193874-0", "RNF-100-3/4-6-SP"			
5053334031	NO			"9-1193880-8", "RNF-100-1-9-SP"			
5053354010	NO			"7-1193883-0", "RNF-100-1-1/2-2-SP"			
5053392064	NO			"7-1193885-6", "RNF-100-2-BK-STK"			
5053442033	NO			"5-1193887-7", "RNF-100-3-BK-STK"			
5053494030	NO			"1-1193889-6", "RNF-100-4-BK-SP"			
5058634002	NO			"2-1193905-8", "RNF-100-1-1/4-2-SP"			
5070024041	NO			"3-1193959-4", "RNF-100-1/16-CL-SP"			
5070122027	NO			"5-1193969-9", "RNF-100-2-CL-STK"			
5200252015	NO			"1194083-1", "CRN-3/16-0-STK"			
539127N001	NO			"6-1194230-8", "RNF-100-1/16-BKSTK-CS5318"			
5426974001	NO			"7-1194254-9", "LSTT-25.4-0-SP"			
5500282020	NO			"6-1194331-8", "SCL-3/16-0-STK", "SCL-3/16-0-STK"			
5509092132	NO			"5-1194348-8", "ATUM-6/2-0-MS-STK"			
5509104074	NO			"1-1194350-1", "ATUM-12/4-0-SP"			
5509122113	NO			"9-1194352-5", "ATUM-40/13-0-MS-STK"			
5510040002	NO			"4-1194354-6", "PD-CAP-1/4-0"			
5677674001	NO			"5-1194500-5", "RNF-3000-24/8-2-SP"			
5677814003	NO			"7-1194504-3", "RNF-3000-24/8-6-SP"			
5677964005	NO			"2-1194511-3", "RNF-3000-39/13-X-SP"			
6009112002	NO			"7-1194754-0", "DWP-125-3/16-0-STK"			
639485M003	NO			"5-1195054-4", "VERSAFIT-3/64-4-SP"			
6645972005	NO			"9-1195236-8", "ZH-100-3/4-0-STK"			
6910104001	NO			"1-1200025-6", "DCPT-51/19-45-SP"			
7145794002	NO			"8-1195592-7", "VERSAFIT-3X-1-0-SP"			
9202774002	NO			"1197141-3", "VERSAFIT-3X-3/4-0-SP"			
934817-000	NO			"4-1197243-9", "RBK-85-KIT-0504-A0"			
9578674002	NO			"1197415-9", "VERSAFIT-3X-1/4-0-SP"			
9617634002	NO			"6-1197440-1", "VERSAFIT-3X-3/8-0-SP", "VERSAFIT 3X"			
9776534001	NO			"6-1197553-1", "CGPT-24/8-X-SP"			
CB5062-000	NO			"9-1899832-1"			
CB5092-000	NO			"5-1899229-9"			
CB5334-000	NO			"3-1899241-6", "SST-48-07/FR/97"			
CB5370-000	NO						
CB5431-000	NO			"6-1899220-7", "XFFR-04X25"			
CB5437-000	NO			"XFFR-11X4", "5-1899230-8"			
CF6166-000	NO			"9-1191306-3"			
CV21064001	NO			"RW-175-E-3/16-X-SP", "6-1899810-2"			
CV25342001	NO			"RW-175-E-1/4-X-STK", "5-1899810-4"			
E32151-000	NO			"8-1200678-8", "VERSAFIT-KIT-4-0"			
E62131-000	NO			"7-1200741-9", "RNF-100-MINI-SPL-1-BK"			
EH2288-000	NO			"DWFR-3/1-0-STK"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
EH2291-000	NO			"DWFR-12/4-0-STK"			
EH2294-000	NO			"DWFR-40/13-0-STK"			
EL6483-000	NO						
EM63392001	NO			"BATTU-20.1/8.9-A1-3-STK"			
EM8986-000	NO						
EM8987-000	NO						
EM8997-000	NO						
F27135-000	NO			"8-1200740-6", "VERSAFIT-MINI-SPL-3/16-BK", "16-0257"			
NB07226001	NO			"BATTU-20.1/8.9-A1-2-51MM"			
NB07236001	NO			"BATTU-20.1/8.9-A1-2-64MM"			
NB07256001	NO			"BATTU-25.4/12.7-A1-2-77MM"			
NB07752001	NO						
NB08082001	NO						
NB09944001	NO						
NB09952001	NO			"ATUM--19/6-0-STK"			
NB10114001	NO						
NB11234001	NO						
NB11382001	NO						
NB11622001	NO						
NB13052001	NO						
NB13264001	NO						
NB14344001	NO						
NB14454001	NO						
NB14534001	NO						
NB14634001	NO						
NB14694001	NO						
NB14932001	NO						
NB15794001	NO						
NB15944001	NO						
NB16054001	NO						
NB16352001	NO						
NB16502001	NO						
NB16964001	NO						
NB16974001	NO						
NB17042001	NO						
NB17734001	NO						
NB17774001	NO						
NB17902001	NO						
NB18084001	NO						
NB18784001	NO						
NB18792001	NO						
NB18932001	NO						
NB19144001	NO						
NB19994001	NO						
NB20164001	NO						
NB20204001	NO						
NB20234001	NO						
NB20374001	NO						
NB20384001	NO						
NB20424001	NO						
NB20474001	NO						
NB20532001	NO						
NB25842001	NO						
NB25902001	NO						

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
085193P003	NO			"9-1190628-5", "ES1000-NO.4-B7-X-STK"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
130599P003	NO			"6-1190948-1", "ES2000-NO.4-B7-0-75MM"			
130599P006	NO			"6-1190948-4", "ES2000-NO.4-B7-0-STK"			
3137794006	NO			"4-1192373-4", "RT-375-1-X-SP"			
349256-000	NO			"4-1200721-0", "VERSAFIT-1/8-KT2-REFILL"			
5053044177	NO			"RNF-100-3/16-BK-SP", "RNF-100-3/16-0", "1832174-1"			
5053392064	NO			"7-1193885-6", "RNF-100-2-BK-STK"			
5053442033	NO			"5-1193887-7", "RNF-100-3-BK-STK"			
5070122027	NO			"5-1193969-9", "RNF-100-2-CL-STK"			
539127N001	NO			"6-1194230-8", "RNF-100-1/16-BKSTK-CS5318"			
5509092132	NO			"5-1194348-8", "ATUM-6/2-0-MS-STK"			
5509122113	NO			"9-1194352-5", "ATUM-40/13-0-MS-STK"			
5510040002	NO			"4-1194354-6", "PD-CAP-1/4-0"			
6009112002	NO			"7-1194754-0", "DWP-125-3/16-0-STK"			
639485M003	NO			"5-1195054-4", "VERSAFIT-3/64-4-SP"			
6645972005	NO			"9-1195236-8", "ZH-100-3/4-0-STK"			
9202774002	NO			"1197141-3", "VERSAFIT-3X-3/4-0-SP"			
CB5334-000	NO			"3-1899241-6", "SST-48-07/FR/97"			
CB5431-000	NO			"6-1899220-7", "XFFR-04X25"			
CB5437-000	NO			"XFFR-11X4", "5-1899230-8"			
E32151-000	NO			"8-1200678-8", "VERSAFIT-KIT-4-0"			
E62131-000	NO			"7-1200741-9", "RNF-100-MINI-SPL-1-BK"			
EM63392001	NO			"BATTU-20.1/8.9-A1-3-STK"			
F27135-000	NO			"8-1200740-6", "VERSAFIT-MINI-SPL-3/16-BK", "16-0257"			
NB07226001	NO			"BATTU-20.1/8.9-A1-2-51MM"			
NB07236001	NO			"BATTU-20.1/8.9-A1-2-64MM"			
NB07256001	NO			"BATTU-25.4/12.7-A1-2-77MM"			
NB09952001	NO			"ATUM--19/6-0-STK"			
NB11382001	NO						
NB11622001	NO						
NB13052001	NO						
NB13264001	NO						
NB14634001	NO						
NB14932001	NO						
NB15794001	NO						
NB15944001	NO						
NB16054001	NO						
NB16352001	NO						
NB16502001	NO						
NB18084001	NO						
NB18784001	NO						
NB18792001	NO						
NB18932001	NO						
NB20204001	NO						
NB20424001	NO						
NB20532001	NO						
NB25842001	NO						

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
085193P006	NO			"9-1190628-8", "ES1000-NO.4-B7-X-50MM"			
130599P007	NO			"6-1190948-5", "ES2000-NO.4-B7-0-60MM"			
130599P011	NO			"6-1190948-8", "ES2000-NO.4-B7-0-50MM"			
3075774001	NO			"6-1192329-0", "HTAT-16/4-0-SP"			
4951524017	NO			"7-1193702-5", "ATUM-32/8-0-SP"			
5052934106	NO			"2-1193826-7", "RNF-100-1/16-WH-SP"			
5053064084	NO			"9-1193841-6", "RNF-100-3/16-YO-SP"			
5053104060	NO			"4-1193848-9", "RNF-100-1/4-RD-SP", "RNF-100-1/4-2"			
5053494030	NO			"1-1193889-6", "RNF-100-4-BK-SP"			
5509104074	NO			"1-1194350-1", "ATUM-12/4-0-SP"			
6910104001	NO			"1-1200025-6", "DCPT-51/19-45-SP"			
7145794002	NO			"8-1195592-7", "VERSAFIT-3X-1-0-SP"			
9202774002	NO			"1197141-3", "VERSAFIT-3X-3/4-0-SP"			
9578674002	NO			"1197415-9", "VERSAFIT-3X-1/4-0-SP"			
9617634002	NO			"6-1197440-1", "VERSAFIT-3X-3/8-0-SP", "VERSAFIT 3X"			
CB5062-000	NO			"9-1899832-1"			
CB5092-000	NO			"5-1899229-9"			
CB5370-000	NO						
CB5437-000	NO			"XFFR-11X4", "5-1899230-8"			
CF6166-000	NO			"9-1191306-3"			

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
085193P006	NO			"9-1190628-8", "ES1000-NO.4-B7-X-50MM"			
130599P006	NO			"6-1190948-4", "ES2000-NO.4-B7-0-STK"			
130599P007	NO			"6-1190948-5", "ES2000-NO.4-B7-0-60MM"			
130599P011	NO			"6-1190948-8", "ES2000-NO.4-B7-0-50MM"			
3075774001	NO			"6-1192329-0", "HTAT-16/4-0-SP"			
3137794006	NO			"4-1192373-4", "RT-375-1-X-SP"			
349256-000	NO			"4-1200721-0", "VERSAFIT-1/8-KT2-REFILL"			
4951524017	NO			"7-1193702-5", "ATUM-32/8-0-SP"			
5052934106	NO			"2-1193826-7", "RNF-100-1/16-WH-SP"			
5053044177	NO			"RNF-100-3/16-BK-SP", "RNF-100-3/16-0", "1832174-1"			
5053064084	NO			"9-1193841-6", "RNF-100-3/16-YO-SP"			
5053104060	NO			"4-1193848-9", "RNF-100-1/4-RD-SP", "RNF-100-1/4-2"			
5053392064	NO			"7-1193885-6", "RNF-100-2-BK-STK"			
5053442033	NO						

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
				"5-1193887-7", "RNF-100-3-BK-STK"			
5053494030	NO			"1-1193889-6", "RNF-100-4-BK-SP"			
5070122027	NO			"5-1193969-9", "RNF-100-2-CL-STK"			
5509092132	NO			"5-1194348-8", "ATUM-6/2-0-MS-STK"			
5509104074	NO			"1-1194350-1", "ATUM-12/4-0-SP"			
5509122113	NO			"9-1194352-5", "ATUM-40/13-0-MS-STK"			
5510040002	NO			"4-1194354-6", "PD-CAP-1/4-0"			
6009112002	NO			"7-1194754-0", "DWP-125-3/16-0-STK"			
639485M003	NO			"5-1195054-4", "VERSAFIT-3/64-4-SP"			
6645972005	NO			"9-1195236-8", "ZH-100-3/4-0-STK"			
6910104001	NO			"1-1200025-6", "DCPT-51/19-45-SP"			
7145794002	NO			"8-1195592-7", "VERSAFIT-3X-1-0-SP"			
9202774002	NO			"1197141-3", "VERSAFIT-3X-3/4-0-SP"			
9578674002	NO			"1197415-9", "VERSAFIT-3X-1/4-0-SP"			
9617634002	NO			"6-1197440-1", "VERSAFIT-3X-3/8-0-SP", "VERSAFIT 3X"			
CB5062-000	NO			"9-1899832-1"			
CB5092-000	NO			"5-1899229-9"			
CB5334-000	NO			"3-1899241-6", "SST-48-07/FR/97"			
CB5370-000	NO						
CB5431-000	NO			"6-1899220-7", "XFFR-04X25"			
CB5437-000	NO			"XFFR-11X4", "5-1899230-8"			
CF6166-000	NO			"9-1191306-3"			
E32151-000	NO			"8-1200678-8", "VERSAFIT-KIT-4-0"			
E62131-000	NO			"7-1200741-9", "RNF-100-MINI-SPL-1-BK"			
EM63392001	NO			"BATTU-20.1/8.9-A1-3-STK"			
F27135-000	NO			"8-1200740-6", "VERSAFIT-MINI-SPL-3/16-BK", "16-0257"			
NB07226001	NO			"BATTU-20.1/8.9-A1-2-51MM"			
NB07236001	NO			"BATTU-20.1/8.9-A1-2-64MM"			
NB07256001	NO			"BATTU-25.4/12.7-A1-2-77MM"			
NB09952001	NO			"ATUM--19/6-0-STK"			
NB11382001	NO						

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
0534174011	NO			"8-1190407-6", "RT-375-3/64-X-SP"			
085193P003	NO			"9-1190628-5", "ES1000-NO.4-B7-X-STK"			
085193P006	NO			"9-1190628-8", "ES1000-NO.4-B7-X-50MM"			
130599P007	NO			"6-1190948-5", "ES2000-NO.4-B7-0-60MM"			
130599P011	NO			"6-1190948-8", "ES2000-NO.4-B7-0-50MM"			
2886154007	NO			"8-1192188-3", "CGAT-24/8-0-SP"			
3075774001	NO			"6-1192329-0", "HTAT-16/4-0-SP"			
3133334001	NO			"2-1192370-4", "CGPT-24/8-9-SP"			
3137794006	NO			"4-1192373-4", "RT-375-1-X-SP"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
5052934106	NO			"2-1193826-7", "RNF-100-1/16-WH-SP"			
5053064027	NO			"9-1193841-4", "RNF-100-3/16-4-SP"			
5053064084	NO			"9-1193841-6", "RNF-100-3/16-YO-SP"			
5053104060	NO			"4-1193848-9", "RNF-100-1/4-RD-SP", "RNF-100-1/4-2"			
5053354010	NO			"7-1193883-0", "RNF-100-1-1/2-2-SP"			
5053494030	NO			"1-1193889-6", "RNF-100-4-BK-SP"			
5070024041	NO			"3-1193959-4", "RNF-100-1/16-CL-SP"			
5200252015	NO			"1194083-1", "CRN-3/16-0-STK"			
5426974001	NO			"7-1194254-9", "LSTT-25.4-0-SP"			
5500282020	NO			"6-1194331-8", "SCL-3/16-0-STK", "SCL-3/16-0-STK"			
5509104074	NO			"1-1194350-1", "ATUM-12/4-0-SP"			
5510040002	NO			"4-1194354-6", "PD-CAP-1/4-0"			
6910104001	NO			"1-1200025-6", "DCPT-51/19-45-SP"			
7145794002	NO			"8-1195592-7", "VERSAFIT-3X-1-0-SP"			
9202774002	NO			"1197141-3", "VERSAFIT-3X-3/4-0-SP"			
934817-000	NO			"4-1197243-9", "RBK-85-KIT-0504-AO"			
9578674002	NO			"1197415-9", "VERSAFIT-3X-1/4-0-SP"			
9617634002	NO			"6-1197440-1", "VERSAFIT-3X-3/8-0-SP", "VERSAFIT 3X"			
CB5062-000	NO			"9-1899832-1"			
CB5370-000	NO						
CB5437-000	NO			"XFFR-11X4", "5-1899230-8"			
CF6166-000	NO			"9-1191306-3"			
CV21064001	NO			"RW-175-E-3/16-X-SP", "6-1899810-2"			
CV25342001	NO			"RW-175-E-1/4-X-STK", "5-1899810-4"			
EH2288-000	NO			"DWFR-3/1-0-STK"			
EH2291-000	NO			"DWFR-12/4-0-STK"			
EH2294-000	NO			"DWFR-40/13-0-STK"			
NB07236001	NO			"BATTU-20.1/8.9-A1-2-64MM"			
NB07256001	NO			"BATTU-25.4/12.7-A1-2-77MM"			
NB07752001	NO						
NB08082001	NO						
NB09944001	NO						
NB10114001	NO						
NB11234001	NO						

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
E32151-000	NO			"8-1200678-8", "VERSAFIT-KIT-4-0"			

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
0534174011	NO			"8-1190407-6", "RT-375-3/64-X-SP"			
085193P003	NO			"9-1190628-5", "ES1000-NO.4-B7-X-STK"			
085193P006	NO			"9-1190628-8", "ES1000-NO.4-B7-X-50MM"			
0893834001	NO			"9-1190655-8", "CGPT-39/13-4-SP"			
130599P007	NO			"6-1190948-5", "ES2000-NO.4-B7-0-60MM"			
130599P011	NO			"6-1190948-8", "ES2000-NO.4-B7-0-50MM"			
2886154007	NO			"8-1192188-3", "CGAT-24/8-0-SP"			
3075774001	NO			"6-1192329-0", "HTAT-16/4-0-SP"			
3133334001	NO			"2-1192370-4", "CGPT-24/8-9-SP"			
3137794006	NO			"4-1192373-4", "RT-375-1-X-SP"			
5052934106	NO			"2-1193826-7", "RNF-100-1/16-WH-SP"			
5053064027	NO			"9-1193841-4", "RNF-100-3/16-4-SP"			
5053064084	NO			"9-1193841-6", "RNF-100-3/16-YO-SP"			
5053104060	NO			"4-1193848-9", "RNF-100-1/4-RD-SP", "RNF-100-1/4-2"			
5053274018	NO			"4-1193874-0", "RNF-100-3/4-6-SP"			
5053334031	NO			"9-1193880-8", "RNF-100-1-9-SP"			
5053354010	NO			"7-1193883-0", "RNF-100-1-1/2-2-SP"			
5053494030	NO			"1-1193889-6", "RNF-100-4-BK-SP"			
5058634002	NO			"2-1193905-8", "RNF-100-1-1/4-2-SP"			
5070024041	NO			"3-1193959-4", "RNF-100-1/16-CL-SP"			
5200252015	NO			"1194083-1", "CRN-3/16-0-STK"			
5426974001	NO			"7-1194254-9", "LSTT-25.4-0-SP"			
5500282020	NO			"6-1194331-8", "SCL-3/16-0-STK", "SCL-3/16-0-STK"			
5509104074	NO			"1-1194350-1", "ATUM-12/4-0-SP"			
5510040002	NO			"4-1194354-6", "PD-CAP-1/4-0"			
5677674001	NO			"5-1194500-5", "RNF-3000-24/8-2-SP"			
5677814003	NO			"7-1194504-3", "RNF-3000-24/8-6-SP"			
5677964005	NO			"2-1194511-3", "RNF-3000-39/13-X-SP"			
6910104001	NO			"1-1200025-6", "DCPT-51/19-45-SP"			
7145794002	NO			"8-1195592-7", "VERSAFIT-3X-1-0-SP"			
9202774002	NO			"1197141-3", "VERSAFIT-3X-3/4-0-SP"			
934817-000	NO			"4-1197243-9", "RBK-85-KIT-0504-A0"			
9578674002	NO			"1197415-9", "VERSAFIT-3X-1/4-0-SP"			
9617634002	NO			"6-1197440-1", "VERSAFIT-3X-3/8-0-SP", "VERSAFIT 3X"			
9776534001	NO			"6-1197553-1", "CGPT-24/8-X-SP"			
CB5062-000	NO			"9-1899832-1"			
CB5092-000	NO			"5-1899229-9"			
CB5370-000	NO						

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
CB5437-000	NO			"XFFR-11X4", "5-1899230-8"			
CF6166-000	NO			"9-1191306-3"			
CV21064001	NO			"RW-175-E-3/16-X-SP", "6-1899810-2"			
CV25342001	NO			"RW-175-E-1/4-X-STK", "5-1899810-4"			
EH2288-000	NO			"DWFR-3/1-0-STK"			
EH2291-000	NO			"DWFR-12/4-0-STK"			
EH2294-000	NO			"DWFR-40/13-0-STK"			
EL6483-000	NO						
EM8986-000	NO						
EM8987-000	NO						
EM8997-000	NO						
NB07236001	NO			"BATTU-20.1/8.9-A1-2-64MM"			
NB07256001	NO			"BATTU-25.4/12.7-A1-2-77MM"			
NB07752001	NO						
NB08082001	NO						
NB09944001	NO						
NB10114001	NO						
NB11234001	NO						
NB14344001	NO						
NB14454001	NO						
NB14534001	NO						
NB14634001	NO						
NB14694001	NO						
NB15794001	NO						
NB15944001	NO						
NB16964001	NO						
NB16974001	NO						
NB17042001	NO						
NB17734001	NO						
NB17774001	NO						
NB17902001	NO						
NB18784001	NO						
NB19144001	NO						
NB19994001	NO						
NB20164001	NO						
NB20204001	NO						
NB20234001	NO						
NB20374001	NO						
NB20384001	NO						
NB20424001	NO						
NB20474001	NO						
NB25902001	NO						