



Product Obsolescence Notification

PCN # 10496977

With Replacement

To: All active customers
From: Rich Benson
cc:
Date March 21, 2011

Part Numbers Affected:		Reason	Timing
75640-0002	Suggest 75640-5002 Tin	No demand	Immediate
75714-0002	Suggest 75714-5002 Tin	No demand	Immediate
75714-0003	Suggest 75714-5003 Tin	No demand	Immediate
75450-0001	Suggest 75450-5001 Tin	No demand	Immediate
75450-0002	Suggest 75450-5002 Tin	No demand	Immediate
75450-0003	Suggest 75450-5003 Tin	No demand	Immediate
75734-0001	Suggest 75734-5001 Tin	No demand	Immediate
75734-0002	Suggest 75734-5002 Tin	No demand	Immediate
75734-0003	Suggest 75734-5003 Tin	No demand	Immediate
75451-0002	Suggest 75451-5002 Tin	No demand	Immediate
75451-0003	Suggest 75714-5003Tin	No demand	Immediate
75462-0001	Suggest 75462-5001 Tin	No demand	Immediate
75451-0001	Suggest 75451-5001 Tin	Little Demand	90 Days
75714-0001	Suggest 75714-5001 Tin	Little Demand	90 Days
75640-0001	Suggest 75640-5001 Tin	Little Demand	90 Days
75640-0003	Suggest 75640-5003 Tin	Little Demand	90 Days

Product Description: Stack SFP Nonlightpipe Tin/lead versions

Replacements: See above

Last Order Entry Date: See effective dates above

Obsolescence Effective Date: March 21, 2011

For further information please contact your local sales representative.

PCN Obsolescence special note: