

ECN/PCN No.: 3535

For Manufacturer			
Product Description: SMD VCXO	Abracon Part Number / Part Series: MVI		<input checked="" type="checkbox"/> Series <input type="checkbox"/> Part Number
Affected Revision: N/A	New Revision: N/A	Application:	<input type="checkbox"/> Safety <input checked="" type="checkbox"/> Non-Safety
Prior to Change: MVI (No PDF or EOL found)			
After Change: Product Series EOL			
Cause/Reason for Change: MVI Product series EOL, See recommended replacement MVIH https://mmdcomp.com/wp-content/uploads/2014/10/MVIH-SERIES.pdf			

Change Plan	
Effective Date: Immediate	Additional Remarks:
Change Declaration:	
Issued Date: <div style="text-align: center;">4/24/20</div>	

For Abracon EOL only		
Last Time Buy (if applicable): None offered	Alternate Part Number / Part Series: <div style="text-align: center;">MVIH</div>	
Additional Approval:	Additional Approval:	Additional Approval:

Customer Approval (If Applicable)		
Qualification Status: <div style="text-align: center;"><input type="checkbox"/> Approved <input type="checkbox"/> Not accepted</div> <i>Note: It is considered approved if there is no feedback from the customer 1 month after ECN/PCN is released.</i>		
Customer Part Number:	Customer Project:	
Company Name:	Company Representative:	Representative Signature:
Customer Remarks:		

Part Number	Series	ECN-EOL #
MVI025HDZH-44.736MHZ	MVI	3535
MVI025HDZH-45.307098MHZ	MVI	3535
MVI025HDZH-45.696MHZ	MVI	3535
MVI025HDZH-50.850992MHZ	MVI	3535
MVI050HDH-19.440MHZ	MVI	3535
MVI3020HCH-19.440MHZ-T	MVI	3535
MVI3025H48PY-100.000MHZ	MVI	3535
MVI3025HPZH-8.064MHZ-T	MVI	3535
MVI3050H48PY-100.000MHZ	MVI	3535
MVI3050HBYH-53.248MHZ	MVI	3535
MVI3050HCZT-27.000MHZ-T	MVI	3535
MVI3050HDH-14.000MHZ	MVI	3535
MVI3050HDH-33.000MHZ	MVI	3535