

<b>Product End Of Life Notification</b>		Date 1/18/2016
<b>Product</b>	Digi EtherLite 32 SKUs	

Reason for Change :

<input type="checkbox"/> Technical Requirement	<input type="checkbox"/> Product Transition
<input type="checkbox"/> Customer Requirement	<input checked="" type="checkbox"/> Product Discontinuation
<input type="checkbox"/> Quality Improvement	<input type="checkbox"/> Product Enhancement
<input type="checkbox"/> Change of Production Location	<input type="checkbox"/> Other (Brand Change)

<b>Description of change</b>	<p>These SKUs are being discontinued due to component obsolescence.</p> <p>Digi will continue to accept orders for these SKUS until <b>June 15, 2016</b>, subject to availability.</p> <p>Delivery of shipments may be scheduled until <b>August 1, 2016</b>.</p>
------------------------------	---

<b>Part Numbers</b>	<p>70001429          EtherLite 32 (Dom)</p> <p>70001533          EtherLite 32 (Int)</p> <p>70001843          EtherLite 32 FAS International</p>
---------------------	---

<b>Timing of Change</b>	<p>Last Time Buy (LTB) = <b>15 June 2016</b></p> <p>Last Shipment Date (LSD) = <b>1 August 2016</b></p>
-------------------------	---

<b>Replacement Product</b> The ConnectPort LTS 32 supports the RealPort driver and offers 32 ports.	<b>EOL SKU</b>	<b>Description</b>	<b>Closest SKU</b>	<b>Description</b>	<b>Notes</b>
	70001429	EtherLite 32 (Dom)	70002411	ConnectPort LTS 32 (Dom)	LTS has different pinout
	70001533	EtherLite 32 (Int)	70002412	ConnectPort LTS 32 (Int)	LTS has different pinout
	70001843	EtherLite 32 FAS (Int)	70002412	ConnectPort LTS 32 (Int)	Requires RealPort driver and LTS pinout



<b>Last Time Buy Part Issues</b>	These SKUs use a number of LTB components. Availability may be limited.
----------------------------------	---

<b>Quality Issues</b>	None
-----------------------	------

<b>Authorization</b>	<i>Ben Tucker Product Manager Digi International</i>
----------------------	--