



# Product Change Notification (PCN)

PCN Number	507001	Date Issued	January 17, 2020
Reason for Change	Retraction		
Change Type Description	This notification is to advise you of a modification to a previously issued PCN. Please refer to the information below for details regarding the amendment.		
Assessment of Change	First article inspection		
Internal Molex Qualification Date			
Sample Availability Date (Changed Part)			
Planned Implementation Date	January 20, 2020		
Method of Identifying Change	Lot information on label		

RELEASED

## After Change

### Overview

- This PCN is a retraction/ recall for previously issued PCN#505402 communicated on for the following:

*PCN505402-50523,50524,50525,50526 add to subcon*

*To add subcontractor to secure customer order. Purpose of notifying customer is to inform customer on the additional subcontractor. There are no impact of the change since there is no change in design, process on the machine, therefore no change in the Molex assembly part number will occur. Sample can be provided upon request. Affected series are 50523,50524,50525 & 50526. As the change will be running change, it can trace by carton label.*

Due to situation change, Molex Malaysia are not add subcontractor for affected series. Product will continue running in-house. This retraction is effective immediately.



## Product Change Notification (PCN)

---

You may address any technical inquiries regarding this PCN by sending E-mail to [pcn\\_coordinator@molex.com](mailto:pcn_coordinator@molex.com) or your Local Sales Engineer.

Note: While responding, please retain "**PCN Notification:507001**" in the e-mail Subject line for faster response.

RELEASED

**Molex, LLC**  
2222 Wellington Court  
Lisle, IL 60532  
TEL: 630-969-4747  
[www.molex.com](http://www.molex.com)

PCN #	Molex Part #
507001	528070610
507001	528072210
507001	528073010
507001	528080470
507001	528080471
507001	528080571
507001	528080670
507001	528080671
507001	528080870
507001	528080871
507001	528081070
507001	528081071
507001	528081170
507001	528081270
507001	528081470
507001	528081471
507001	528081570
507001	528081670
507001	528081771
507001	528081870
507001	528082070
507001	528082071
507001	528082271
507001	528082371
507001	528082470
507001	528082471
507001	528082670
507001	528083070
507001	528083071

#

**Part numbers affected:**

52807-0610
52808-0470
52808-1371
52808-1870
52808-2071

#