

Light is OSRAM

Product Or Individual Q-Code Discontinuation (acc. JEDEC J-STD-048)  
**OS-PDN-2021-028**

01 April 2021


---

Last order: 02 April 2021

---

Last delivery: 31 May 2021

---



Please direct your feedback to your local Sales office.

DISCONTINUED				NEW (REPLACEMENT)		
Device	Ordering Code	Brand	Reason for discontinuation	Device	Datasheet Ordering Code	Brand
GWM JTL6SA.EM-1213-6501-1-60-R18	Q65113A0205	DURIS	Discontuniation of MMP Device			No replacement
GWM JTL6SA.EM-1314-5702-1-60-R18	Q65113A0206	DURIS	Discontuniation of MMP Device			No replacement
GWM JTL6SA.EM-1314-5003-1-60-R18	Q65113A0207	DURIS	Discontuniation of MMP Device			No replacement
GWM JTL6SA.EM-1314-4005-1-60-R18	Q65113A0208	DURIS	Discontuniation of MMP Device			No replacement
GWM JTL6SA.EM-1213-3007-1-60-R18	Q65113A0209	DURIS	Discontuniation of MMP Device			No replacement
GWM JTL6SA.EM-1012-2708-1-60-R18	Q65113A0210	DURIS	Discontuniation of MMP Device			No replacement
GWM JTLPSD.EM-L1L1-4005-1-150-R33	Q65112A9809	DURIS	Discontuniation of MMP Device			No replacement
GWM JTLPSD.EM-L1L1-5003-1-150-R33	Q65112A9810	DURIS	Discontuniation of MMP Device			No replacement
GWM JTLPSD.EM-L1L1-6501-1-150-R33	Q65112A9811	DURIS	Discontuniation of MMP Device			No replacement
GWM JTLRSA.CM-L1L2-2908-1-100-R33	Q65112A9524	DURIS	Discontuniation of MMP Device			No replacement
GWM JTLRSA.CM-L1L2-2708-1-100-R33	Q65112A9525	DURIS	Discontuniation of MMP Device			No replacement
GWM JTLRSA.CM-L1L2-3007-1-100-R33	Q65112A9668	DURIS	Discontuniation of MMP Device			No replacement
GWM JTLRSA.CM-L1L2-AS37-1-100-R33	Q65112A9912	DURIS	Discontuniation of MMP Device			No replacement
GWM JTLRSA.EM-0912-2210-1-100-R18	Q65113A0188	DURIS	Discontuniation of MMP Device			No replacement
GWM JTLRSA.EM-1013-2708-1-100-R18	Q65113A0194	DURIS	Discontuniation of MMP Device			No replacement
GWM JTLRSA.EM-1016-4005-1-100-R18	Q65113A0195	DURIS	Discontuniation of MMP Device			No replacement
GWM JTLRSA.EM-1016-6501-1-100-R18	Q65113A0196	DURIS	Discontuniation of MMP Device			No replacement
GWM JTLRSA.EM-1016-5003-1-100-R18	Q65113A0197	DURIS	Discontuniation of MMP Device			No replacement

DISCONTINUED				NEW (REPLACEMENT)		
Device	Ordering Code	Brand	Reason for discontinuation	Device	Datasheet Ordering Code	Brand
GWM JTLRSA.EM-1016-5702-1-100-R18	Q65113A0198	DURIS	Discontuniation of MMP Device			No replacement
GWM JTLRSA.EM-1014-3007-1-100-R18	Q65113A0204	DURIS	Discontuniation of MMP Device			No replacement
GWM JTLRSA.EM-1417-6501-1-100-R18	Q65113A1285	DURIS	Discontuniation of MMP Device			No replacement
GWM JTLRSA.EM-1417-5702-1-100-R18	Q65113A1286	DURIS	Discontuniation of MMP Device			No replacement
GWM JTLRSA.EM-1417-5003-1-100-R18	Q65113A1287	DURIS	Discontuniation of MMP Device			No replacement
GWM JTLRSA.EM-1417-4005-1-100-R18	Q65113A1288	DURIS	Discontuniation of MMP Device			No replacement
GWM JTLRSA.EM-1317-3506-1-100-R18	Q65113A1289	DURIS	Discontuniation of MMP Device			No replacement
GWM JTLRSA.EM-1316-3007-1-100-R18	Q65113A1290	DURIS	Discontuniation of MMP Device			No replacement
GWM JTLRSA.EM-1215-2708-1-100-R18	Q65113A1291	DURIS	Discontuniation of MMP Device			No replacement
GWM JTLRSA.PM-1416-5702-1-100-R18	Q65113A1163	DURIS	Discontuniation of MMP Device			No replacement
GWM JTLRSA.PM-1416-5003-1-100-R18	Q65113A1164	DURIS	Discontuniation of MMP Device			No replacement
GWM JTLRSA.PM-1416-4005-1-100-R18	Q65113A1165	DURIS	Discontuniation of MMP Device			No replacement
GWM JTLRSA.PM-1416-3506-1-100-R18	Q65113A1166	DURIS	Discontuniation of MMP Device			No replacement
GWM JTLRSA.PM-1415-3007-1-100-R18	Q65113A1167	DURIS	Discontuniation of MMP Device			No replacement
GWM JTLRSA.PM-1314-2708-1-100-R18	Q65113A1168	DURIS	Discontuniation of MMP Device			No replacement
GWM JTLRSA.PM-1416-6501-1-100-R18	Q65113A1173	DURIS	Discontuniation of MMP Device			No replacement
GWM JTLRSB.CM-L1L2-6201-1-100-R33	Q65112A9523	DURIS	Discontuniation of MMP Device			No replacement
GWM JTLRSB.CM-L1L2-7501-1-100-R33	Q65112A9526	DURIS	Discontuniation of MMP Device			No replacement

DISCONTINUED				NEW (REPLACEMENT)		
Device	Ordering Code	Brand	Reason for discontinuation	Device	Datasheet Ordering Code	Brand
GWM JTLRSB.CM-L1L2-7201-1-100-R33	Q65112A9913	DURIS	Discontuniation of MMP Device			No replacement
GWM JTLRSB.CM-L1L2-5702-1-100-R33	Q65113A1170	DURIS	Discontuniation of MMP Device			No replacement
GWM JTLRSB.CM-L1L2-5003-1-100-R33	Q65113A1171	DURIS	Discontuniation of MMP Device			No replacement
GWM JTLRSB.CM-L1L2-4005-1-100-R33	Q65113A1172	DURIS	Discontuniation of MMP Device			No replacement
GWM JTLRSB.EM-L1-3007-1-100-R33	Q65113A0189	DURIS	Discontuniation of MMP Device			No replacement
GWM JTLRSB.EM-L1-2708-1-100-R33	Q65113A0190	DURIS	Discontuniation of MMP Device			No replacement
GWM JTLRSB.EM-L1-4005-1-100-R33	Q65113A0191	DURIS	Discontuniation of MMP Device			No replacement
GWM JTLRSB.EM-L1-5003-1-100-R33	Q65113A0192	DURIS	Discontuniation of MMP Device			No replacement
GWM JTLRSB.EM-L1-6501-1-100-R33	Q65113A0193	DURIS	Discontuniation of MMP Device			No replacement