



# Product Change Notification

## TE Connectivity

Product Change Notification: E-14-013059

PCN Date: 30-SEP-14

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:  
1355524 - MQS, COVER, 12 POS.

Description of Changes  
Added rib in cover, so that it acts as stopper for socket housing from entering/assembling in wrong/incorrect position above guiding feature in section A-A and drawing Modified for centric tolerance.  
Other attachments:  
[1355524 - PDF](#)

Reason for Changes:  
Product Improvement. There is a possibility of Socket housing being assembled in wrong/incorrect position. To avoid this, a rib is added in cover. This modification applies only for new tool that is being built.  
Estimated Dates:  
Last Order Date (Obsolete Parts Only):  
First Date To Ship (Changed Parts Only):  
03-SEP-2015  
Last Ship Date (Obsolete Parts Only):  
Last Date for Mixed Shipments: (Changed Parts Only):  
03-SEP-2016

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">1-1355524-3</a>	NO					

The documents listed below are being modified. Related parts that are not explicitly listed on this PCN are not being modified or discontinued as per the PCN. The Last Order Date, Last Ship Date, First Date to Ship Changed Parts and last date for Mixed Shipments apply only to parts explicitly listed on this PCN.

Customer Drawing(s) Being Modified:

Drawing Number	Current Revisor	New Revisor
<a href="#">1355524</a>	D1	