



Product Change Notification

TE Connectivity

Product Change Notification: P-16-013564

PCN Date: 14-SEP-16

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:
USB2.0 TYPE A RECEPTACLE ASSEMBLY, T/H TYPE

Description of Changes
Obsolete PN 1932854-1 by PM Egbert's request

Reason for Changes:
Part status change. Not able to support any more for this USB due to tooling scraped already
Estimated Dates:
Last Order Date (Obsolete Parts Only): 15-DEC-2016 First Date To Ship (Changed Parts Only):
Last Ship Date (Obsolete Parts Only): 19-DEC-2016 Last Date for Mixed Shipments: (Changed Parts Only): No Mixed Shipments

Part Number(s) being Modified:

| Part Number | Part Discontinued per PCN | Customer Drawing | Customer Part Number | Alias Part Number(s) | Substitute Part Number | Substitute Alias Part Number(s) | Description Of Difference |
|-------------|---------------------------|------------------|----------------------|----------------------|------------------------|---------------------------------|---------------------------|
| 1932854-1 | YES | | | | | | |

Part Number(s) being Modified:

| Part Number | Part Discontinued per PCN | Customer Drawing | Customer Part Number | Alias Part Number(s) | Substitute Part Number | Substitute Alias Part Number(s) | Description Of Difference |
|-------------|---------------------------|------------------|----------------------|----------------------|------------------------|---------------------------------|---------------------------|
| 1932854-1 | YES | | | | | | |

Part Number(s) being Modified:

| Part Number | Part Discontinued per PCN | Customer Drawing | Customer Part Number | Alias Part Number(s) | Substitute Part Number | Substitute Alias Part Number(s) | Description Of Difference |
|-------------|---------------------------|------------------|----------------------|----------------------|------------------------|---------------------------------|---------------------------|
| 1932854-1 | YES | | | | | | |

Part Number(s) being Modified:

| Part Number | Part Discontinued per PCN | Customer Drawing | Customer Part Number | Alias Part Number(s) | Substitute Part Number | Substitute Alias Part Number(s) | Description Of Difference |
|-------------|---------------------------|------------------|----------------------|----------------------|------------------------|---------------------------------|---------------------------|
| 1932854-1 | YES | | | | | | |

Part Number(s) being Modified:

| Part Number | Part Discontinued per PCN | Customer Drawing | Customer Part Number | Alias Part Number(s) | Substitute Part Number | Substitute Alias Part Number(s) | Description Of Difference |
|---------------------------|---------------------------|------------------|----------------------|----------------------|------------------------|---------------------------------|---------------------------|
| 1932854-1 | YES | | | | | | |

Part Number(s) being Modified:

| Part Number | Part Discontinued per PCN | Customer Drawing | Customer Part Number | Alias Part Number(s) | Substitute Part Number | Substitute Alias Part Number(s) | Description Of Difference |
|---------------------------|---------------------------|------------------|----------------------|----------------------|------------------------|---------------------------------|---------------------------|
| 1932854-1 | YES | | | | | | |