

# TE Connectivity

Product Change Notification: E-15-012438

## PCN Date: 12-OCT-15

## TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

### General Product Description: 2.5 SDL 18P CAP & PLUG HSG

#### Description of Changes

Rib extrude for improve mis-matching (P/N:2108504-1,2108505-1) This change is considered by TE Connectivity as a; . Location of change, see

Reason for Changes:						
Customer Request. Customer request						
Estimated Dates:	istimated Dates:					
Last Order Date (Obsolete Parts Only):	First Date To Ship (Changed Parts Only):					
	11-NOV-2015					
Last Ship Date (Obsolete Parts Only):	Last Date for Mixed Shipments: (Changed Parts Only):					
	18-NOV-2015					

### Part Number(s) being Modified:

Part	Part Discontinued	Customer	<b>Customer Part</b>	Alias Part	Substitute Part	Substitute Alias	Description Of
Number	per PCN	Drawing	Number	Number(s)	Number	Part Number(s)	Difference
2108504-1	NO						
2108505-1	NO						

#### Part Number(s) being Modified:

	Part	Part Discontinued	Customer	<b>Customer Part</b>	Alias Part	Substitute Part	Substitute Alias	Description Of
	Number	per PCN	Drawing	Number	Number(s)	Number	Part Number(s)	Difference
2	108504-1	NO						
2	108505-1	NO						

Part Number(s) being Modified:

Part	Part Discontinued	Customer	<b>Customer Part</b>	Alias Part	Substitute Part	Substitute Alias	Description Of
Number	per PCN	Drawing	Number	Number(s)	Number	Part Number(s)	Difference
2108504-1	NO						
2108505-1	NO						