



Product Change Notification (PCN)



PCN Number	510685	Date Issued	September 13, 2021
Reason for Change	Change to Product		
Change Type Description	This letter is to inform you that changes are being made to the part(s) identified in this Notice. The change may affect the fit, form, function or appearance of the parts, or it may result in a change to the specification. The details below show an example of the possible differences.		
Reason for Short Notice	Corrective Actions		
Assessment of Change	Product will be fully qualified before it is shipped. Qualification reports will be available after below listed date		
Internal Molex Qualification Date	August 12, 2021		
Sample Availability Date (Changed Part)	August 12, 2021		
Planned Implementation Date	October 13, 2021		
Method of Identifying Change	Date code		

RELEASED


Before Change

- Change carrier tape design for micro-USB 105017-1001.

Before change: 105017-1001 used the same carrier tape with 105017-0001



After change: design new carrier tape for 105017-1001.



After Change

Overview

- There is risk that connector 105017-1001 is slant in old carrier tape because the original carrier tape is designed for 105017-0001, the slant risk will impact customer SMT pick and place process. The slant risk will be improved by using the new carrier tape.
- Product Impact
 - No impact to fit, form or function of connector itself.
 - Will improve customer SMT pick and place process
- Part Number Impact
 - 105017-1001



Product Change Notification (PCN)

You may address any technical inquiries regarding this PCN by sending E-mail to pcn_coordinator@molex.com or your Local Sales Engineer.

Note: While responding, please retain "**PCN Notification:510685**" in the e-mail Subject line for faster response.

RELEASED

Molex, LLC
2222 Wellington Court
Lisle, IL 60532
TEL: 630-969-4747
www.molex.com