



PRODUCT CHANGE NOTIFICATION

E-Switch Series/ Part No affected: 34-HY386B8021000, 34-HY386E8021000, 34-HY386E8021211	Part /Series Description: HY38-6B8-021-000, HY38-6E8-021-000, HY38-6E8-021-211
---	--

Affected Process

Assembly
 Molding
 Stamping
 Plating

Change on:

Drawing
 Process
 Material
 Specification
 Packaging
 Tooling Modification
 New Tooling
 Manufacturing Location
 Others

Reason for change:

1. This product family became obsolete in 2018, but notifications were not issued.
- 2.

Proposed change:

1. **Parts are made OBSOLETE.**

Proposed Transition/change over:

ECO will be created to make all 3 parts obsolete.

Customer Notification

Action Item:
