



Product Change Notification		Date June 15, 2021
Product	Connect IT 4/16/48/Mini	

Description of change	New firmware version 21.5.56.108 available for all Connect IT products. This is a major production release. Digi recommends all customers update their Connect IT products to firmware v21.5.56.108
------------------------------	---

Reason for Change	New Firmware Version 21.5.56.108 provides: <ul style="list-style-type: none">• New Features• Enhancements• Bug Fixes• Security Fixes See Release Notes for more details.
--------------------------	---

Product Notice	<p>A new stable firmware version has been released for the Connect IT products, version 21.5.56.108. Use the link below to view the full list of changes, features, and fixes included in the new firmware.</p> <p>Connect IT Release Notes</p> <p><u>To take advantage of the new features, you must take action to update your device.</u> Refer to the instructions to update your firmware in the release notes above for more information.</p> <p>Any questions or concerns about the new firmware, or for assistance updating your device(s), please contact the Digi Support team at tech.support@digi.com.</p>
-----------------------	--

Affected Part Numbers	IT16-1002, IT48-1002, IT01-M100, ASB-5402-RM
------------------------------	--

Timing of Change	Effective Immediately
-------------------------	-----------------------