

Dear Valued Trinamic Customer,

This is to inform you about a bill of material change effective immediately, which affects the cable looms listed in the table below. In order to reduce the number of SKUs, we no longer offer these cable looms. Instead, please only use the order code of the corresponding replacement parts listed in the table. Each replacement part includes the identical set of cables with the addition of one extra motor connector cable.

Changes

The following changes have been applied:

- The PANdrive related cable looms (PD-xxxx-CABLE) will be replaced by the corresponding module cable loom (TMCM-xxxx-CABLE). The cable looms will thus contain one additional motor connector cable.

Compatibility

Notes on compatibility:

- The replacement parts are fully compatible as the cable looms only include one additional motor connector cable.

This improvement is classified as a minor change.

Products Affected

Products Affected		Replacement Parts	
Order Code	Article Number	Order Code	Article Number
PD-1021-CABLE	71-0031	TMCM-1021-CABLE	71-0012
PD-1060-CABLE	71-0030	TMCM-1060-CABLE	71-0011
PD-1070-CABLE	71-0045	TMCM-1070-CABLE	71-0046
PD-1076-CABLE	71-0057	TMCM-1076-CABLE	71-0058
PD-110-CABLE	71-0022	TMCM-110-CABLE	71-0002
PD-1140-CABLE	71-0036	TMCM-1140-CABLE	71-0019
PD-1141-CABLE	71-0035	TMCM-1141-CABLE	71-0017
PD-1160-CABLE	71-0037	TMCM-1160-CABLE	71-0020
PD-1161-CABLE	71-0032	TMCM-1161-CABLE	71-0013
PD-1180-CABLE	71-0029	TMCM-1180-CABLE	71-0009
PD-1210-CABLE	71-0062	TMCM-1210-CABLE	71-0044
PD-1240-CABLE	71-0050	TMCM-1240-CABLE	71-0051
PD-1241-CABLE	71-0055	TMCM-1241-CABLE	71-0054
PD-1260-CABLE	71-0052	TMCM-1260-CABLE	71-0053
PD-1270-CABLE	71-0047	TMCM-1270-CABLE	71-0048
PD-1276-CABLE	71-0061	TMCM-1276-CABLE	71-0060
PD-1278-CABLE	71-0066	TMCM-1278-CABLE	71-0067
PD-140-CABLE	71-0028	TMCM-140-CABLE	71-0008

If you have any questions, please contact your sales partner.