

| | |
|---------------------|--|
| NO: Sw - 139 | PRODUCT: SEPARATOR FOR SS/V – Basic Switch Separator |
| DATE: November 2022 | TYPE: DISCONTINUATION – Streamline Product Offering |

SEPARATOR FOR SS/V Basic Switch Separator – DISCONTINUED IMMEDIATELY

In an effort to streamline our product offering and focus on popular models of Omron’s line of Basic Switch Separators, Omron will discontinue several Separator for SS / V accessories **effective immediately**. The suggested replacements will be our SEPARATOR FOR SS T0.13 and SEPARATOR FOR V T0.13 models. Please carefully read through this notification and note the differences. The following details will fully explain the discontinuation and suggested replacement considerations; should you have any additional questions, however, please communicate with the Switch Product Manager, Roland Hiso.

Discontinuation date:
Effective Immediately



Differences from discontinued product:





| Suggested replacement Model | Body Color | Dimen-sions | Wire connection | Mounting Dimensions | Charact-eristics | Operation ratings | Operation methods |
|---|------------|-------------|-----------------|---------------------|------------------|-------------------|-------------------|
| SEPARATOR FOR SS T0.13 SEPARATOR FOR V T0.13 | -- | * | ** | ** | ** | ** | ** |

- ** : Compatible
- * : The change is a little/Almost compatible
- : Not compatible
- : No corresponding specification



Discontinued Models and Suggested Replacement:

| Discontinued Model | Suggested Replacement |
|-----------------------|------------------------|
| SEPARATOR FOR SS 0.18 | SEPARATOR FOR SS T0.13 |
| SEPARATOR FOR SS 0.4 | |
| SEPARATOR FOR V 0.18 | SEPARATOR FOR V T0.13 |
| SEPARATOR FOR V 0.25 | |

Body Color:

| Discontinued Product Model SEPARATOR FOR SS/V 0.18 | Suggested Replacement Model SEPARATOR FOR SS/V T0.13 |
|--|---|
| <p>SEPARATOR FOR SS 0.18</p>  | <p>SEPARATOR FOR SS T0.13</p>  |
| <p>SEPARATOR FOR V 0.18</p>  | <p>SEPARATOR FOR V T0.13</p>  |

Dimensions:

| Discontinued Product Model SEPARATOR FOR SS/V | Suggested Replacement Model SEPARATOR FOR SS/V T0.13 |
|---|---|
| <p>Thickness</p> <p>SEPARATOR FOR SS 0.18 : T0.18 SEPARATOR FOR SS 0.4 : T0.4</p> <p>SEPARATOR FOR V 0.18 : T0.18 SEPARATOR FOR V 0.25 : T0.25</p> | <p>Thickness</p> <p>SEPARATOR FOR SS T0.13 : T0.13 SEPARATOR FOR SS T0.13 : T0.13</p> <p>SEPARATOR FOR V T0.13 : T0.13 SEPARATOR FOR V T0.13 : T0.13</p> |
| <p>Dimensions</p> <p>SEPARATOR FOR SS 0.18 SEPARATOR FOR SS 0.4</p>  <p>SEPARATOR FOR V 0.18 SEPARATOR FOR V 0.25</p>  | <p>Dimensions</p> <p>SEPARATOR FOR SS T0.13</p> <p>No changes</p> <p>SEPARATOR FOR V T0.13</p> <p>No changes</p> |

* Sales teams should communicate this discontinuation with their OEM's and CEM's.
For further technical support and any questions, please communicate with Product Marketing.

Specifications in this product news are as of the issue date and are subject to change without notice. Only main changes in specifications are described in this document. Please be sure to read the relevant catalogs, datasheets, product specifications, instructions, and manuals for precautions and necessary information when using products.
This PCN is intended for use in the Americas
Last time buy dates are subject to change based on availability