

# PRODUCT CHANGE NOTIFICATION

PCN#: TIES AND TERMINALS

20190405-1

ISSUE DATE:

5-Apr-19

IMPACTED REGIONS:

NA

EMEA

LATAM

AP

REASON FOR CHANGE:

DISCONTINUATION

OTHER

**DESCRIPTION OF CHANGE: (Not Required for discontinuation)**

Panduit has discontinued the following part numbers: PN22-10R-C, PN22-10R-M, PN22-2F-M, PN22-2R-C, PN22-2R-M, PN22-8R-C, PN22-8R-M, PV22-2R-CY, and PV22-2R-MY. Please note that the #4 and #6 stud hole size products of these families will

**IMPACTED PART NUMBERS AND REPLACEMENT PART NUMBERS: (where applicable)**

[Reference Page 2 / Linked PDF](#)

**DATES: DISCONTINUATION AND NEW PRODUCT AVAILABILITY:**

SCHEDULE FOR CHANGE	Year (YYYY)	Month (MM)	Day (DD)
New product sample availability date			
Old product discontinuation date*	2019	4	5

**\*Important:** After old product discontinuation date, the affected part numbers listed above will continue to be available for sale as long as supplies last. Product may be returned up to 60 days after the product continuation date.

IMPACTED PART NUMBER(s)	REPLACEMENT PART NUMBER(s)
PN22-10R-C	PV22-10R-CY
PN22-10R-M	PV22-10R-MY
PN22-2F-M	PV22-2R-MY**
PN22-2R-C	PV22-2R-CY
PN22-2R-M	PV22-2R-MY
PN22-8R-C	PV22-8R-CY
PN22-8R-M	PV22-8R-CY
PV22-2F-CY	PV22-2R-CY**
PV22-2F-MY	PV22-2R-MY**
* Insulating material considerations should be made for potential crosses	
** No fork type connector available with equivalent stud size	