

Notification of Product Recall

Notification Date: August 26, 2015

Recall Notification Number: OPR1001

Affected Part Numbers: OPL6000

Affected Date Codes All date codes

Description of Defect The OPL6000 switches the logic output state when the input is idle for an extended duration. This causes an undesired and unexpected behavior in the product.

Required Action: Distributors should return all existing inventory.

Return of Product: Contact your respective Customer Service Representative for RMA and instructions for return.

Recall Authorization:



Jeff Beatty
Product Marketing Specialist
TT Electronics Sensing and Control
Optoelectronics Business Unit