



Product Obsolescence Notification: TW5340/41/43

Released: February 7, 2022

Effective: August 31 2021

Discontinued Products

- TW5340 – GPS L1/ GLONASS G1 + SBAS Smart Antenna (Timing)
- TW5341 – Non-magnetic GPS L1/ GLONASS G1 + SBAS smart antenna (Timing)
- TW5343 – GPS L1/ GLONASS G1 + SBAS Smart Antenna (2* RS422 outputs)

As a part of our continuous commitment to provide customers with the most current technology and best experience, Tallysman is discontinuing manufacturing selected products from our standard product offerings due excessive lead on certain components from our supply chain.

Tallysman has served the industrial market and we understand the importance of the industrial market life cycle. However, in today's rapidly changing world, components become obsolete for many reasons, including continual advances in technologies. We will make our best effort to provide a product with the same functionality and quality.

Recommended Alternative Product Lines

The following products are form fit and function compatible with the TW534X products except for the 1PPS qualification output, please contact Tallysman for additional information.

- TW5350 – GPS L1/ GLONASS G1 + SBAS Smart Antenna (Timing)
- TW5351 – Non-magnetic GPS L1/ GLONASS G1 + SBAS smart antenna (Timing)
- TW5353 – GPS L1/ GLONASS G1 + SBAS Smart Antenna (2* RS422 outputs)
-

Warranty and After Market Parts Support for Obsoleted Products

Standard Tallysman warranty terms are applicable.

We apologize for any inconvenience this announcement may cause and remain eager to meet your future requirements. Should you have any question about this notification, please do not hesitate to contact us.