



Eaton  
Electronics Division  
5735 W. Las Positas Blvd #100  
Pleasanton, CA 94588  
[www.eaton.com/electronics](http://www.eaton.com/electronics)

## Product Change Notice

PCN#: EE-PCN22003

January 20, 2022

### CLASSIFICATION OF CHANGE:

Manufacturing Location

### DESCRIPTION OF CHANGE:

There has been a manufacturing location change for select 1/4" fuse clips from the USA to Taiwan. Please refer to the parts affected list on the second page.

### REASON FOR CHANGE:

This change has been implemented to streamline manufacturing operations.

### EXPECTED INFLUENCE ON QUALITY, RELIABILITY, AND PERFORMANCE:

There will be no effect on the quality, reliability, or performance. There are no changes to form, fit, and function of the devices.

### TIME SCHEDULE:

Effective February 14, 2022

### ISSUED BY:

Jenan Krouchick  
Product Manager – Circuit Protection

### CONTACT INFORMATION:

For questions or comments, please contact your local [Eaton sales representative](#).

<b>Affected Part Number:</b>
1A1119-04-R
1A1119-05
1A1119-10
1A1120-06
1A1907-03-R
BK-1A1119-04-R
BK-1A1119-05
BK-1A1119-10-R
BK-1A1120-05
BK-1A1120-06-R
BK-1A1120-09-R
BK-1A1907-03-R
BK-1A1907-05
BK-1A1907-06-R
BK-1A3398-07-R
BK-1A4533-01-R
BK-1A4533-06-R
BK-1A4534-01-R
BK-1A4534-06-R