


Light is OSRAM

Product Or Individual Q-Code Discontinuation (acc. JEDEC J-STD-048)
OS-PDN-2021-119

01 November 2021

Last order: 01 May 2022
Last delivery: 01 November 2022



Please direct your feedback to your local Sales office.

DISCONTINUED				NEW (REPLACEMENT)		
Device	Ordering Code	Brand	Reason for discontinuation	Device	Datasheet Ordering Code	Brand
BPX 38	Q62702P0015	Metal Can	material discontinuation	no replacement		
BPX 38-3	Q62702P0015S003	Metal Can	material discontinuation	no replacement		
BPX 38-4	Q62702P0015S004	Metal Can	material discontinuation	no replacement		
BPX 43	Q62702P0016	Metal Can	material discontinuation	no replacement		
BPX 43-4	Q62702P0016S004	Metal Can	material discontinuation	no replacement		
BPX 43-5	Q62702P0016S005	Metal Can	material discontinuation	no replacement		
BPX 38-2/3	Q62702P3578	Metal Can	material discontinuation	no replacement		
BPX 43-3/4	Q62702P3581	Metal Can	material discontinuation	no replacement		
BPX 43-4/5	Q62702P3582	Metal Can	material discontinuation	no replacement		
BPX 43-5 E9519	Q62702P5349	Metal Can	material discontinuation	no replacement		

Ordering Code	Notification	Device	Product Descr.	Brand	Reason	Repl. Product Descr.	Repl. Ordering Code
Q62702P0015	OS-PDN-2021-119	BPX 38	BPX 38	Metal Can	material discontinuation		
Q62702P0015S003	OS-PDN-2021-119	BPX 38	BPX 38-3	Metal Can	material discontinuation		
Q62702P0015S004	OS-PDN-2021-119	BPX 38	BPX 38-4	Metal Can	material discontinuation		
Q62702P0016	OS-PDN-2021-119	BPX 43	BPX 43	Metal Can	material discontinuation		
Q62702P0016S004	OS-PDN-2021-119	BPX 43	BPX 43-4	Metal Can	material discontinuation		
Q62702P0016S005	OS-PDN-2021-119	BPX 43	BPX 43-5	Metal Can	material discontinuation		
Q62702P3578	OS-PDN-2021-119	BPX 38	BPX 38-2/3	Metal Can	material discontinuation		
Q62702P3581	OS-PDN-2021-119	BPX 43	BPX 43-3/4	Metal Can	material discontinuation		
Q62702P3582	OS-PDN-2021-119	BPX 43	BPX 43-4/5	Metal Can	material discontinuation		
Q62702P5349	OS-PDN-2021-119	BPX 43	BPX 43-5 E9519	Metal Can	material discontinuation		