

Product Change Notice

PCN#: EE-PCN17047

12/04/2017

CLASSIFICATION OF CHANGE:


Specification correction

DESCRIPTION OF CHANGE:

Correct the recommended PCB layout for FP1109B1-R. Please refer to diagram below.



Previous spec.



New spec.

REASON FOR CHANGE:

The previous recommended PCB layout doesn't match the pin dimension well. Corrected the specification to match the pin dimension.

EXPECTED INFLUENCE ON QUALITY, RELIABILITY, AND PERFORMANCE:

There will be no effect on the quality, reliability, or performance. There are no changes to form, fit, and function of the devices.

PARTS FAMILIES AFFECTED:

FP1109B1-R150-R
FP1109B1-R180-R
FP1109B1-R220-R
FP1109B1-R300-R

ISSUED BY:

Global Product Manager: Steve Subiry

CONTACT INFORMATION:

For questions or comments, please contact your local [Eaton sales representative](#).