

Global Change Notification (GCN)

Product Family	PCB TABS	10731637
		GCN Number
Series	36662 below mentioned part numbers	November 23, 2015
		Date Issued
Reason For Change	Obsolescence	
Change Description	<p>The GCN is created for obsoleting the part numbers belonging to Series 36662. These parts are stamped as loose terminals and barrel plated at outside vendor. Due to barrel plating issues, 100% sorting has to be done after plating and the rejection rate varies from 15%~25%. The sorting hours spent is not justified financially as the volume is too less. In-house plating can not be done as copper under coat plating facility is not available, also die modification to make terminals in chain form is not viable financially. Part numbers: 366620001 , 366620002, 366620003, 366620004, 366620005, 366620006, 368800001</p>	
Part Numbers Affected	Please refer to CustomerPartList.csv attached to e-mail message.	
Reason For Short Notice Exception	Not Applicable	
Assessment Of Change (How Product Will Be Qualified & Validated)	NA	
Internal Molex Qualification Date (Planned Date Information Available)		
Sample Availability Date (Changed Part)		
Date of Implementation	December 31, 2016	
Method of Identifying Change	NA	
Recommended Replacement Parts	No replacement	
Last Time Buy Date for Obsolete Parts	December 31, 2016	
Last Time Ship Date for Obsolete Parts	January 06, 2017	

Contact	Name	E-mail	Phone Number
Sales Engineer	Please refer to e-mail message for your local sales engineer.		
Regional Coordinator (Japan and Korea)	Naomi Maruyama	Naomi.Maruyama@molex.co.jp	+81-46-265-2416
Regional Coordinator (Asia- excluding Japan and Korea)	Allen Yu	Allen.Yu@molex.com	+886-2-66251751
Regional Coordinator (Europe, Middle East, Africa)	Agnes Mburu	Agnes.Mburu@molex.com	+31-40-295-8271
Regional Coordinator (Americas)	Maria Sullivan	Maria.Sullivan@molex.com	1-727-322-4352

Molex, Inc.
 2222 Wellington Court
 Lisle, IL 60532
 TEL: 630-969-4747
www.molex.com