



# Product Change Notification

<b>Date Issued :</b>	June 22, 2022	<b>PCN Number :</b>	512250
<b>Reason for Change :</b>	Obsolete		
<b>Description of Change :</b>	This notification is to inform you that Molex will no longer support this product due Toray resin compromised UL qualification. UL qualification of UL94V-0 for the original Resin from Toray has changed due to the thickness change from 0.38mm to 1.5mm. Accordingly, all references in Sales Drawings to UL94V-0 should be disregarded.		
<b>Reason for Short Notice :</b>	Special Request		
<b>Planned Implementation Date :</b>	April 15, 2023		
<b>Recommended replacement parts :</b>	Please see the attached replacement parts list .xls file.		
<b>Last Time Buy Date for Obsolete Parts :</b>	December 31, 2022		
<b>Last Time Ship Date for Obsolete Parts :</b>	March 31, 2023		

# RELEASED

After Picture

## Overview

- This notification is to inform you that Molex will no longer support this product due Toray resin compromised UL qualification.

UL qualification of UL94V-0 for the original Resin from Toray has changed due to the thickness change from 0.38mm to 1.5mm. Accordingly, all references in Sales Drawings to UL94V-0 should be disregarded.

- Product Impact
  - Obsolescence with Replacement (Refer to PCN #512016)
    - See attached for Impacted part list vs Replacement Part List
    - Replacement Part is No impact to Form, Fit or Function.
    - Please refer to above for LTB and LTS dates

Contents	Impacted	Replacement
Part Number	51281**94	51281**98
Resin	TORAY LCP UL-94 V0 (disregarded)	SUMITOMO LCP UL-94 V0

1

Molex Confidential Information  
© 2016 Molex – All Rights Reserved. Unauthorized Reproduction/Distribution is Prohibited.



# RELEASED

"After the last time ship date, Molex will no longer manufacture the products included within this notification and all related tooling will be decommissioned.

For assets that are customer owned, the owner has 90 days after the last time ship date to claim the tooling."

You may address inquires regarding this PCN by clicking on the below link

[mailto:pcn\\_coordinator@molex.com?subject=PCN\\_Notification:512250](mailto:pcn_coordinator@molex.com?subject=PCN_Notification:512250)

or contact your Local Sales Engineer.

Note: While responding, please retain " PCN Notification : **PCN Notification: 512250** " in the e-mail Subject line for faster response.

[Molex, LLC](#)

2222 Wellington Court

Lisle, IL 60532

TEL (800) 786-6539

[www.molex.com](http://www.molex.com)

Molex Part Number	Replacement part number:
512812694	512812698
512812494	512812498
512812294	512812298
512812094	512812098
512811894	512811898
512811694	512811698
512811494	512811498
512811294	512811298
512811194	512811198
512811094	512811098
512810994	512810998
512810894	512810898
512810794	512810798
512810694	512810698
512810594	512810598