

Global Change Notification (GCN)

Product Family	2W NSCC Pin Conn.	10684406
		GCN Number
Series	98822, 68800	May 28, 2015
		Date Issued
Reason For Change	New, Modified, Or Replacement Tooling	
Change Description	This letter is to announce a second assembly machine to make 2 way NSCC connectors is being built to allow Molex to meet current demand.	
Part Numbers Affected	Please refer to CustomerPartList.csv attached to e-mail message.	
Reason For Short Notice Exception	New Capacity	
Assessment Of Change (How Product Will Be Qualified & Validated)	All product from the second machine will be qualified by Molex before it is shipped. PPAP documentation will be provided upon request.	
Internal Molex Qualification Date (Planned Date Information Available)	May 05, 2015	
Sample Availability Date (Changed Part)	May 05, 2015	
Date of Implementation	June 29, 2015	
Method of Identifying Change	Product made after May 26, 2015 can contain this change	
Recommended Replacement Parts	Not Applicable	
Last Time Buy Date for Obsolete Parts		
Last Time Ship Date for Obsolete Parts		

Contact	Name	E-mail	Phone Number
Sales Engineer	Please refer to e-mail message for your local sales engineer.		
Regional Coordinator (Japan and Korea)	Naomi Maruyama	Naomi.Maruyama@molex.co.jp	+81-46-265-2416
Regional Coordinator (Asia- excluding Japan and Korea)	Allen Yu	Allen.Yu@molex.com	+886-2-66251751
Regional Coordinator (Europe, Middle East, Africa)	Agnes Mburu	Agnes.Mburu@molex.com	+31-40-295-8271
Regional Coordinator (Americas)	Maria Sullivan	Maria.Sullivan@molex.com	1-727-322-4352

Molex, Inc.
 2222 Wellington Court
 Lisle, IL 60532
 TEL: 630-969-4747
www.molex.com