

Date: June 29, 2018
To: Bussmann series fuseclip and fuse block customers
Subject: End-of-life notification

Dear valued customer:

Effective immediately, the Bussmann™ series fuseclips and blocks in the table below are obsolete. While there are no direct replacements for form and fit, we do offer similar products that may be substituted.

Existing inventory is saleable product and should not be returned.

| Catalog no. | UPC | Catalog no. | UPC | Catalog no. | UPC |
|-------------|--------------|--------------|--------------|-------------|--------------|
| 3529 | 051712222570 | 5682-41 | 051712739313 | 5681-08 | 051712739276 |
| 4121 | 051712737906 | 5682-44 | 051712739320 | 5681-15-R | 051712648523 |
| 4531 | 051712738736 | 5682-44-R | 051712648530 | 5672-11 | 051712739238 |
| 4560 | 051712224352 | BK-1A4005-06 | 051712137027 | 5674-41 | 051712739252 |
| 4567 | 051712224376 | BK-5678-14 | 051712137591 | 5956-16 | 051712739337 |
| 3434BS | 051712736756 | BK-5678-15 | 051712137690 | 5960-51 | 051712814980 |
| 4512NGC | 051712142441 | BK-5681-15 | 051712137713 | 5961-21 | 051712226202 |
| 5672-11 | 051712739238 | BK-5681-15-R | 051712649988 | 5960-53 | 051712231848 |
| 5672-11-R | 051712648493 | BK-5682-41 | 051712137850 | 5960-61-R | 051712648554 |
| 5681-08 | 051712739276 | BK-5682-41-R | 051712649063 | 5960-62-R | 051712648561 |
| 5681-15 | 051712739283 | BK-5682-44 | 051712137874 | 5960-63-R | 051712648578 |
| 5681-15-R | 051712648523 | BK-5682-44-R | 051712649094 | 5591-42 | 051712149952 |
| 5682-14 | 051712127851 | 5591-52 | 051712739214 | 5592-11 | 051712225670 |

For assistance in selecting a replacement product, contact FuseTech@Eaton.com, or your Bussmann series product sales representative.

Kind regards,



AJ Johnson
Product Manager