

## 1 Products affected

Product hierarchy no. *				Part no.	SBU	Type / Description	Customer part no.
SBU	PG	PUG	Type				
01	002	003	0000000680	0031.1681 0031.1757 0031.1758 3-108-568	Circuit Protection	FEU (Med)	n/a

\*SBU (2-digit) / PG (3-digit) / PUG (3-digit) / Type (10-digit)

## 2 Type of change

- Change of material

## 3 Detailed description of change

The material of the fuse holder socket has been changed from thermoset to thermoplastic. This change has neither an effect on the performance nor on the specifications. The approvals have been updated to reflect the changes.

Old product appearance	New product appearance
Slightly shiny surface	Matt surface
Old material	New material
Thermoset: Phenolic resin	Thermoplastic: PPA

## 4 Reason of change

- Better availability of thermoplastic material
- State of the art production process

## 5 Release date

The change takes effect in week 20/2022 (Date code 2220 or higher on label).

## 6 Impact of change and recommended action

Form	Yes	No action required
Fit	No	-
Function	No	-
Manufacturing	No	-
Label	No	-
Packaging	No	-

## 7 Reference Documents / Attachments

Kind of document	Remarks
<a href="#">Data Sheet</a>	FEU (Med)

Product Change Notification					PCN FEU (Med) material change		
owner	creation date	release date	released by	change order no	rev	page	D10-061-106
zeierjo	27.10.2021	25.11.2021	schulejo	2020908	A	1 of 1	