



Product Change Notification

TE Connectivity

Product Change Notification: P-22-022357

PCN Date: 16-MAR-22

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:

MICRODOT Products

Description of Changes

Dear Customer, as a result of our continuous improvement process we hereby inform you of a supplier change to our MICRODOT product. The following Part Numbers will now be plated in our TE Connectivity facility located in Hermosillo, MX. This will not affect form-fit-function in any way.

Reason for Changes:

Capacity and quality improvement initiatives. Dear Customer, we hereby inform you about the additional plating facility for added plating capacities. The additional location follows a strict procedure, which fully maintains quality, ability to supply and form-fit-function of the concerned products. The addition of the new plating location will have a positive impact to the current capacity and quality of our TE Connectivity MICRODOT products. The scope change is limited to only Housing Shell.

Estimated Dates:

Last Order Date (Obsolete Parts Only):	First Date To Ship (Changed Parts Only):
	27-MAY-2022
Last Ship Date (Obsolete Parts Only):	Last Date for Mixed Shipments: (Changed Parts Only):
	17-APR-2023

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1-1532009-9	NO			"094-0706-0014", "MCK-C2-B-51S6A7-18.0"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1-1532189-1	NO			"095-0286-1004"			
1-1532238-2	NO			"095-0785-1010", "MCDM1-B-51P4D1-30.0"			
1-1532244-4	NO			"095-0507-0506", "MCDM1-P-15P/15S4L4-X"			
1-1532244-6	NO			"095-0507-0508", "MCDM1-P-31P/31S4L4-X"			
1466111-1	NO			"132-0117-0003"			
1466289-1	NO			031-0059-0001			
1466296-1	NO			AC-G03294-M, 033-0101-0001			
1467950-1	NO			132-0116-0002			
1495144-1	NO			"095-9088-7161", "MCEMX-128SRAW/SEAL"			
1532009-1	NO			"094-0616-2002", "MCK-C2-RM-37S6G7-50.0"			
2-1532009-0	NO			"094-0706-0017", "MCK-C2-B-51S6G7-36.0"			
2-1532009-3	NO			"094-0706-0027", "MCK-C2-B-51S6G7-12.0"			
2-1532024-6	NO			"095-9085-5165", "MCDM1-P-51PS"			
3-1532009-3	NO			"094-0716-2001", "MCK-C2-RM-51S6G7-50.0"			
3-1532024-1	NO			"095-9086-1575", "MCDMX-B-15SX-0.5SPLEPOXY"			
4-1532004-5	NO			033-0102-0001			
4-1532018-6	NO			"095-0088-7116", "MCEM1-128SRA"			
4-1532243-5	NO			"095-0785-1011", "MCDM1-LM-51P6A7-18.0"			
5-1532017-4	NO			"095-0085-3161", "MCDM1-B-31P6G7-36.0"			
5-1532017-6	NO			"095-0085-3166", "MCDM1-B-31P4C7-36.0"			
5-1532150-1	NO			"095-0085-3169", "MCDM1-B-31P4D2-12.0"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
6-1532016-5	NO			094-9606-0016, MCK-N1-B-37S6Q9-18.0			
6-1532017-4	NO			"095-0085-5105", "MCDM1-B-51P4D1-12.0"			
6-1532017-5	NO			"095-0085-5115", "MCDM1-B-51P4D1-24.0"			
6-1532017-6	NO			"095-0085-5120", "MCDM1-B-51P6D1-12.0"			
6-1532017-9	NO			"095-0085-5170", "MCDM1-B-51P6A7-18.0"			
6-1532024-5	NO			"095-9088-7162", "MCEMX-128SX"			
6-1532028-2	NO			"K95-9091-1098"			
6-1532028-4	NO			033-0090-0001			
6-1532158-6	NO			"094-0606-0016", "MCK-C2-B-37S6A7-18.0"			
6-1532159-3	NO			"095-0085-3172", "MCDM1-B-31P6G7-72.0"			
6-1532159-4	NO			"095-0785-1005", "MCDM1-B-51P6G7-72.0"			
6-1532160-3	NO			"094-0716-2003"			
6-1532236-2	NO			"095-0286-1009", "MCDM1-B-15S6D1-11.0"			
6-1532245-2	NO			"094-0616-7001"			
6-1532246-3	NO			"095-0785-1012", "MCDM1-B-51P4A9-40.0"			
7-1532017-0	NO			"095-0085-5181", "MCDM1-B-51P6G7-36.0"			
7-1532017-1	NO			"095-0085-5187", "MCDM1-B-51P6L4-2.0"			
7-1532017-4	NO			"095-0085-5192", "MCDM1-B-51P4C7-18.0"			
7-1532017-9	NO			"095-0086-1500", "MCDM1-B-15S4L4-0.5"			
7-1532240-7	NO			"095-0085-3175", "MCDM1-B-31P4C1-36.0"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
7-1532246-8	NO			"095-0286-1011", "MCDM1-B-15S6D1-16.0"			
7-1925009-1	NO			"N12763"			
8-1532017-0	NO			"095-0086-1525", "MCDM1-B-15S6A7-12.0"			
8-1532017-1	NO			"095-0086-1567", "MCDM1-B-15S6D1-24.0"			
8-1532129-1	NO			"094-9706-0048", "MCK-XX-B-51SX"			
8-1532154-8	NO			"094-9606-9013", "MCK-N1-X1-37SX"			
8-1589678-6	NO			"SSL05110242PC2DC012"			
9-1532004-7	NO			"053-0752-0001"			
9-1532137-0	NO			"051-0607-0001"			
9-1532157-1	NO			"094-0706-0036", "MCK-C2-B-51S6A7-72.0"			
9-1532233-7	NO			"095-0286-1008", "MCDM1-P-15S6G7-18.0"			