

PRODUCT CHANGE NOTIFICATION

Product Category SAFETY PRODUCTS 20221026-1

Product Group ID AND SAFETY

ISSUE DATE: 26-Oct-22

IMPACTED REGIONS: NA EMEA LATAM AP

REASON FOR CHANGE: DISCONTINUATION
 OTHER

DESCRIPTION OF CHANGE: (Required)

Part numbers PLVS0507W7163, PRS1014D7133, PRS1014D7345, and PRS1014D7346 will be discontinued.

Photos/Drawing (where applicable)

IMPACTED PART NUMBERS AND REPLACEMENT PART NUMBERS: (where applicable)

[Reference Page 2 / Linked PDF](#)

DATES: DISCONTINUATION AND NEW PRODUCT AVAILABILITY:

SCHEDULE FOR CHANGE	Year (YYYY)	Month (MM)	Day (DD)
New product sample availability date	2022	10	26
Old product discontinuation date*	2023	1	24

***Important:** A return material authorization (RMA) may be obtained for these affected part numbers and they may be returned up to 60 days after the product discontinuation announcement date if purchased within the last 18 months and subject to the return policy requirements outlined in Panduit’s Authorized Distributor Policy. Please contact your local Panduit Customer Experience team if you have any questions.

IMPACTED PART NUMBER(s)	Compatibility Type	Replacement Part 1	Discontinuation Date
PLVS0507W7163	Compatible	PVS0305W2102Y	24-Jan-23
PRS1014D7133	Compatible	PRS1014D73	24-Jan-23
PRS1014D7345	No Replacement	NO-REPLACEMENT	24-Jan-23
PRS1014D7346	No Replacement	NO-REPLACEMENT	24-Jan-23