

PRODUCT CHANGE NOTIFICATION

Product Category SAFETY PRODUCTS 20230228-1

Product Group ID AND SAFETY

ISSUE DATE: 28-Feb-23

IMPACTED REGIONS: NA EMEA LATAM AP

REASON FOR CHANGE: DISCONTINUATION
 OTHER

DESCRIPTION OF CHANGE: (Required)

Discontinuation of Grainger-specific Safety Product part numbers. Thanks for your ongoing support.

Photos/Drawing (where applicable)

IMPACTED PART NUMBERS AND REPLACEMENT PART NUMBERS: (where applicable)

[Reference Page 2 / Linked PDF](#)

DATES: DISCONTINUATION AND NEW PRODUCT AVAILABILITY:

SCHEDULE FOR CHANGE	Year (YYYY)	Month (MM)	Day (DD)
New product sample availability date	2023	2	28
Old product discontinuation date*	2023	5	29

***Important:** A return material authorization (RMA) may be obtained for these affected part numbers and they may be returned up to 60 days after the product discontinuation announcement date if purchased within the last 18 months and subject to the return policy requirements outlined in Panduit’s Authorized Distributor Policy. Please contact your local Panduit Customer Experience team if you have any questions.

CUSTOMER SERVICE CONTACTS

ASIA PACIFIC	AUSTRALIA: 1-800 7263848 AUS-CSVM@panduit.com	CHINA: 400-820-1900 CHN-CustomerService@panduit.com	HONG KONG: 800-965768 CHN-CustomerService@panduit.com	
	INDIA: 000 800 6501844 (Fixed) 000 800 6500369 (Mobile) SGP-Customer_Service@panduit.com	INDONESIA: 001 803 65 7571 SGP-Customer_Service@panduit.com	JAPAN: +81-3-6863-6000 JPN-CS@panduit.com	
	KOREA: 02-2182-7300 KOR-CustomerService@panduit.com	MALAYSIA 1800 801435 SGP-Customer_Service@panduit.com	SINGAPORE: 1-800-7263848 SGP-Customer_Service@panduit.com	
	TAIWAN: 0080 165 1487 SGP-Customer_Service@panduit.com	THAILAND: 001-800-65-6385 SGP-Customer_Service@panduit.com		
	LATIN AMERICA	BRAZIL 08000562613 (Toll Free) BRA-custservice@panduit.com	MEXICO: +52-33-37776000 x80520 01 800 360 86 00 (Toll Free) MEX-customerService@panduit.com	OTHER LA COUNTRIES: Phone USA 1-708-532-1800 TP-CS-INTERNATIONAL@panduit.com
NORTH AMERICA	USA & CANADA: 1-800-777-3300 cs@panduit.com	EMEA FORM C2-1003 DATE: 06 APR 21 APPR. MURILLO	EMEA: +44 208 6017219 EMEA-CustomerServices@panduit.com	

IMPACTED PART NUMBER(s)	Replacement Part 1	Replacement Part 2
GPSL-KT-MROG	PSL-KT-CONA	
GPSL-KT-MROG	PSL-KT-MROA	
GPSL-PK-EG	NO-REPLACEMENT	
PLD-52G	PLD-52	
PLD-56G	PLD-56	
PLD-57G	PLD-57	
PSL-CBG	PSL-CB	
PSL-CBGM	PSL-CB	
PSL-CBILG	PSL-CBIL	
PSL-CBILNTG	PSL-CBILNT	
PSL-CBILNTGM	PSL-CBILNT	
PSL-CBKITG	PSL-CBKIT	
PSL-CBLG	PSL-CBL	
PSL-CBLGM	PSL-CBL	
PSL-CBNTG	PSL-CBNT	
PSL-CBNTGM	PSL-CBNT	
PSL-ERBG	NO-REPLACEMENT	
PSL-MCBNTG	PSL-MCBNT	
PSL-MLDG	PSL-MLD	
PSL-MLDGM	PSL-MLD	
PSL-PCBNTG	PSL-PCBNT	
PSL-PCBNTGM	PSL-PCBNT	
PSL-PG	PSL-P	
PSL-PIG	PSL-PI	
PSL-PL1BKYG	PSL-PL1REDY	
PSL-PL1BLKYG	PSL-PL1REDY	
PSL-PL1BLUYG	PSL-PL1REDY	
PSL-PL1BUYG	PSL-PL1REDY	
PSL-PL1GRNYG	PSL-PL1REDY	
PSL-PL1GRYG	PSL-PL1REDY	
PSL-PL1REDYG	PSL-PL1REDY	
PSL-PL1WHTYG	PSL-PL1REDY	
PSL-PL1WHYG	PSL-PL1REDY	
PSL-PL1YELYG	PSL-PL1REDY	
PSL-PL1YLYG	PSL-PL1REDY	
PSL-WSG	PSL-WS	
PVS0204C171YGA	NO-REPLACEMENT	
PVS0204C176YGA	T200X000VX1Y	TDP43ME
PVS0204C177YGA	T200X000VX1Y	TDP43ME
PVS0204C178YGA	T200X000VX1Y	TDP43ME
PVS0204C179YGA	C400X600A61	TDP43ME
PVS0204W172YGA	T200X000VX1Y	TDP43ME
PVS0503N458YG	NO-REPLACEMENT	