

# Product Change Notification (PCN)

PCN Number	502631	Date Issued	March 29, 2017
Reason for Change	Packaging Method/Quantity Changing		
Change Type Description	This letter is to inform you that the part(s) referenced in this notice will undergo packaging specification changes that may include new container sizes and quantities. No changes will be made to the product as a result of the packaging change.		
Reason for Short Notice	Corrective Actions		
Planned Implementation Date	March 31, 2017		

## Before Change

- Reel of Ribbon wire with UL processed wire respooled label



## After Change

### Overview

- This PCN is to replace PCN 501519 due to mistake of change type and missing detail of before and after
- REMOVE, UL PROCESSED WIRE RESPOOLED label Due to splitting process ribbon cable is not in UL PROCESSED WIRE RESPOOLED definition.

- Product Impact
  - no impact to any fit, form or function
- Part Number Impact
  - see attached impacted parts list



Molex Confidential Information



## Product Change Notification (PCN)

---

You may address any technical inquiries regarding this PCN by sending E-mail to [pcn\\_coordinator@molex.com](mailto:pcn_coordinator@molex.com) or your Local Sales Engineer.

Note: While responding, please retain "**PCN Notification:502631**" in the e-mail Subject line for faster response.

RELEASED

**Molex, LLC**  
2222 Wellington Court  
Lisle, IL 60532  
TEL: 630-969-4747  
[www.molex.com](http://www.molex.com)

Molex Part #

82226102

82226104

82283020

82283040

82286161