



Expertise Applied | Answers Delivered

8755 W. Higgins Road
Suite 500
Chicago, IL 60631
www.littelfuse.com

September 25, 2017

LF PCN# C0171 Supply Interruption & Product Change Notice.

Part #: BMIB025.Z; BMIB020.Z

Dear Valued Customer,

Littelfuse would like to notify you of our inability to supply the following parts as of this date due to factors beyond our control.

As a result, we are offering the following products as replacement when current stock is depleted. The form of these parts is slightly different. Please see pictures below. However fit and function remain the same. This is a running change effective as of September 25, 2017. Similarly, the packaged materials will also be made up with the proposed material.

Current/Obsolete Material	Proposed New Material	Affected Packaged Material
BMIB025.Z	30419-25	0MIB025.X
BMIB020.Z	30419-20	0MIB020.X

Picture of discontinued product



Picture of replacement product



Please contact your local sales representatives for any further information.

Thank you for your continued support.

Best Regards,

Guerton Auguste

Product Manager

gauguste@littelfuse.com