



October 21, 2020

RedRock® RR111 / RR121 / RR131 End-Of-Life (EOL) Product Notification

Last Time Buy (LTB) Date: February 1, 2021

Last Time Ship (LTS) Date: June 1, 2021

Attention: All RedRock® RR111/121/131 TMR Magnetic Sensor Customers

Coto Technology prides itself on continued improvement through investments, research, and development of new innovative products. From time to time, this product development results in older parts becoming obsolete when compared to newer parts with overall improved performance. Therefore, we want to ensure that you are made aware – in a timely manner – that Coto will be obsoleting the RR111, RR121 and RR131 series’ sensors by June 1, 2021.

Coto will no longer recommend these sensors for new designs but, instead, will provide alternate solutions from our recently released RR112, RR122, RR132 and RR142 series’ product offerings. These parts are form, fit and functionally equivalent to the earlier series’ while offering even lower supply current and broader voltage range (both features requested by demand by many of our customers). Our Application Support Engineers are ready and able to assist with any product changeover questions or inquiries.

PN's Affected	Suggested Replacement *
RR111-1DC2-331**	RR112-1G42-531**
RR111-1DC2-332**	RR112-1G42-532**
RR121-1A23-311	RR122-1A23-511
RR121-1A53-311	RR122-1A53-511
RR121-1B13-311	RR122-1B13-511
RR121-1B13-312	RR122-1B13-512
RR121-1B53-311	RR122-1B53-511
RR121-1B93-312	RR122-1B93-512
RR121-1E73-311	RR122-1E73-511
RR121-2A32-364	RR122-2E22-511 (x2) RR122-2E23-511 (x2)
RR121-3C63-311	RR122-3C63-511
RR121-3C73-311	RR122-3C73-511
RR121-2E22-311	RR122-2E22-511
RR131-1B13-351	RR132-1B13-551
RR131-1B13-352	RR132-1B13-552
RR131-2E23-351	RR132-2E23-551

* RR112/RR122/RR132 part numbers available in both temperatures -40°C to +85°C and -40°C to +125°C.

** Please note the difference in sensitivity and range values.

Last Time Buy (LTB) of these RedRock® products is February 1, 2021 with a Last Time Ship (LTS) date of June 1, 2021. If you have any questions, please contact your local Coto Sales Representative or your Account Manager. If you are in need of further support in the form of product specifications, samples and/or technical support when converting from RR111, RR121 or RR131 to RR112, RR122 or RR132, please contact appsupport@cotorelay.com.

Sincerely,

William Gotschewski
Vice President, Product & Technology