



Discontinuation Notice for ELL-5PR, ELL-5PS, and ELL-SFG Series Surface Mount Chip Choke Coils

PDN.PG47.4.01.2015

04/01/2015

Effective Date:	April 1, 2015
Last Time Buy Date:	June 30, 2015
Last Time Ship Date:	September 30, 2015
Discontinuation Details:	As a result of decreased market demand Panasonic is discontinuing the ELL-5PR, ELL-5PS, and ELL-SFG Series Surface Mount Chip Choke Coils . There are no direct replacements for these parts.
Suggested Replacement:	No direct replacements
Affected Part Numbers:	See attached.
Datasheets:	http://industrial.panasonic.com/www-data/pdf/AGM0000/AGM0000CE17.pdf http://industrial.panasonic.com/www-data/pdf/AGM0000/AGM0000CE7.pdf http://industrial.panasonic.com/www-data/pdf/AGM0000/AGM0000CE5.pdf
Notes:	

Affected Part Numbers

ELL-5PR100M
ELL-5PR1R0N
ELL-5PR1R2N
ELL-5PR1R5N
ELL-5PR2R2N
ELL-5PR3R3N
ELL-5PR4R7N
ELL-5PR6R8N
ELL-5PRR47N
ELL-5PS100M
ELL-5PS101M
ELL-5PS150M
ELL-5PS1R2N
ELL-5PS1R5N
ELL-5PS220M
ELL-5PS2R2N
ELL-5PS2R7N
ELL-5PS330M
ELL-5PS3R3N
ELL-5PS470M
ELL-5PS4R7N
ELL-5PS560M
ELL-5PS680M
ELL-5PS820M
ELL-SFG100MA
ELL-SFG101MA
ELL-SFG121MA
ELL-SFG150MA
ELL-SFG151MA
ELL-SFG181MA
ELL-SFG1R0NA
ELL-SFG1R2NA
ELL-SFG220MA
ELL-SFG221MA
ELL-SFG2R2NA
ELL-SFG330MA
ELL-SFG331MA
ELL-SFG3R3NA
ELL-SFG470MA
ELL-SFG471MA
ELL-SFG4R7NA
ELL-SFG560MA
ELL-SFG680MA
ELL-SFG6R8NA

ELL-SFG820MA