

## PRODUCT DISCONTINUATION NOTIFICATION

**PDN No.: USA2011 / 009**

**Issue Date: 10/11/2011**

IXYS Corporation has found it necessary to discontinue certain products. This notification is to inform you that this change may affect your products. If you have any comments on the discontinuation please fill out and return the attached customer response form on Page 2 within 30 days of the PDN Issue date.

<b>REASON FOR DISCONTINUATION:</b>			
No demand for devices in leaded TO-268 package for 5 years			
<b>PDN TIME LINE:</b>			
<b>LAST TIME ORDER DATE: OCT. 31 2011</b>			
<b>LAST TIME DELIVERY DATE: NOV. 01 2011</b>			
IXYS Part No.:	Product Type:	Manufactured Since:	Recommended Replacement:
<b>IXTJ36N20</b>			NO REPLACEMENT
<b>IXFJ32N50Q</b>			NO REPLACEMENT
<b>IXFJ40N30</b>			NO REPLACEMENT
<b>IXGJ40N60C2D1</b>			NO REPLACEMENT
<b>IXGJ50N60B</b>			NO REPLACEMENT
<b>PDN CREATED/UPDATED</b>			
DATE: 11/4/11			
ORIGINATOR: V. Tsukanov, VP R&D Power MOS Products			
REVIEWED BY: Gordon Rosete, Dir. QA-QC			

**IF 0266 REV. B**

**PRODUCT DISCONTINUATION NOTIFICATION**

**PDN No.:** USA2011 / 009

**Issue Date:** 10/11/2011

**CUSTOMER RESPONSE:**

Company: \_\_\_\_\_ Date: \_\_\_\_\_

Name: \_\_\_\_\_ Position: \_\_\_\_\_

Phone/Fax/e-mail: \_\_\_\_\_

**Comments:**

---

**RETURN TO:** IXYS CORPORATION  
JOSIE VELACION  
QA/QC DEPT. HEAD  
1590 BUCKEYE DRIVE, MILPITAS, CA 95035-7418  
PHONE: +1-408-457-9085  
E-MAIL: [j.velacion@ixys.net](mailto:j.velacion@ixys.net)