



Product Discontinuance Notice - PDN 22_0116 Rev. -

Analog Devices, Inc. One Analog Way, Wilmington, MA 01887

This notice is to inform you of a product discontinuance for certain ADI products (see Discontinued Parts Material List below). Any issues with this PDN must be sent to ADI as soon as possible. The information contained within this PDN is considered proprietary and should not be shared outside of your company. ADI contact information is listed below.

PDN Title:

Obsolescence of LTM90xx Family of Signal Chain uModule High Speed Receivers

Publication Date: 23-Jan-2023

Last Time Buy Date: 16-Jan-2023

Last Time Ship Date: 31-Jan-2024

Revision Description:

Initial Release

Reason For Discontinuance

Manufacturability of this family of products is being discontinued.

Supporting Documents None

For questions on this PDN, send email to the regional contacts below or contact your local ADI sales representative

Americas: PDN_Americas@analog.com

Europe: PDN_Europe@analog.com

Japan: PDN_Japan@analog.com

Rest of Asia: PDN_ROA@analog.com

PDN 22_0116 Discontinued Parts Material List

Model	Product Family	Replacement Part	Pin To Pin Compatible	Comments
DC1298A-LA	LTM9002	none	n/a	
DC1513B-AA	LTM9004	none	n/a	
DC1513B-AD	LTM9004	none	n/a	
DC1931B	LTM9013	none	n/a	
DC4846B	LTM9004	none	n/a	
LTM9002CV-AA#PBF	LTM9002	AD9648BCPZ-125	no	
LTM9002CV-LA#PBF	LTM9002	AD9648BCPZ-125	no	
LTM9002IV-AA#PBF	LTM9002	AD9648BCPZ-125	no	
LTM9002IV-LA#PBF	LTM9002	AD9648BCPZ-125	no	
LTM9003CV-AA#PBF	LTM9003	AD9697BCPZ-1300	no	Direct RF sampling architecture
LTM9003CV-AB#PBF	LTM9003	AD9697BCPZ-1300	no	Direct RF sampling architecture
LTM9003IV-AA#PBF	LTM9003	AD9697BCPZ-1300	no	Direct RF sampling architecture
LTM9003IV-AB#PBF	LTM9003	AD9697BCPZ-1300	no	Direct RF sampling architecture
LTM9004CV-AA#PBF	LTM9004	AD9697BCPZ-1300	no	Direct RF sampling architecture
LTM9004CV-AB#PBF	LTM9004	AD9697BCPZ-1300	no	Direct RF sampling architecture
LTM9004CV-AC#PBF	LTM9004	AD9697BCPZ-1300	no	Direct RF sampling architecture
LTM9004CV-AD#PBF	LTM9004	AD9697BCPZ-1300	no	Direct RF sampling architecture
LTM9004IV-AA#PBF	LTM9004	AD9697BCPZ-1300	no	Direct RF sampling architecture

LTM9004IV-AB#PBF	LTM9004	AD9697BCPZ-1300	no	Direct RF sampling architecture
LTM9004IV-AC#PBF	LTM9004	AD9697BCPZ-1300	no	Direct RF sampling architecture
Model	Product Family	Replacement Part	Pin To Pin Compatible	Comments
LTM9004IV-AD#PBF	LTM9004	AD9697BCPZ-1300	no	Direct RF sampling architecture
LTM9012CY-AB#PBF	LTM9012	AD9675KBCZ	no	Octal channel only or standalone quad ADC AD9253
LTM9012IY-AB#PBF	LTM9012	AD9675KBCZ	no	Octal channel only or standalone quad ADC AD9253
LTM9013CY-AA#PBF	LTM9013	AD9697BCPZ-1300	no	Direct RF sampling architecture
LTM9013IY-AA#PBF	LTM9013	AD9697BCPZ-1300	no	Direct RF sampling architecture

Appendix A - PDN 22_0116 Revision History

Rev	Publish Date	Rev Description
Rev. -	23-Jan-2023	Initial Release

Analog Devices, Inc. Proprietary Information

DocId:1901 Layout Rev:3 Parent DocId:None