

# Product Discontinuation



## PD\_081\_21

■ Last Order Date:	2023-02-28
■ Last Delivery Date:	2023-08-31

Reason: Product portfolio rationalization

DISCONTINUED				NEW (REPLACEMENT)			
Sales Name	SP Number	OPN	Package	Sales Name	SP Number	OPN	Package
TDA5103A	SP000305485	TDA5103AHTMA1	PG-TSSOP-10			none	
TDA5150	SP000300415	TDA5150HTMA1	PG-TSSOP-10			none	
TDA7100	SP000296466	TDA7100HTMA1	PG-TSSOP-10			none	
TDA7110F	SP000611108	TDA7110FHTMA1	PG-TSSOP-10			none	
TDA7116F	SP000611114	TDA7116FHTMA1	PG-TSSOP-10			none	
TDK5100F	SP000014745	TDK5100FHTMA1	PG-TSSOP-10			none	
TDK5101F	SP000014744	TDK5101FHTMA1	PG-TSSOP-10			none	
TDK5110F	SP000056180	TDK5110FHTMA1	PG-TSSOP-10			none	
TDK5111F	SP000056181	TDK5111FHTMA1	PG-TSSOP-10			none	
TDK5116F	SP000056182	TDK5116FHTMA1	PG-TSSOP-10			none	
TX98-3	SP000743718	TX983HTMA1	PG-TSSOP-10			none	
TX98-4	SP000743714	TX984HTMA1	PG-TSSOP-10			none	

If you have any questions, please do not hesitate to contact your local sales office.

**Disclaimer:** The supply of this product will stop after the date of last delivery as outlined herein. Final orders can only be accepted on or before the last order date and are subject to the availability. Early ordering is strongly recommended! If Infineon confirms a purchase order with a delivery date beyond last delivery date, the PD with the mentioned last ordering date still remains valid.