

Date: January 17, 2018
To: Bussmann series 3998 fuse block customers
Subject: End-of-life notification

Dear valued customer:

Effective immediately, the Bussmann™ series 3998 fuse block for ¼" x 1 ¼" fuses is discontinued. The recommended replacement for fit and function is listed in the table below.

Catalog no.	Description	UPC	Replacement*	UPC
3998	¼" x 1 ¼" Fuse block	051712738415	BK-S-8002-1X-R	051712559379

* Catalog number is for bulk quantity of 1000 blocks.

Any existing inventory of this fuse block is saleable product and should not be returned.

For further assistance, contact FuseTech@Eaton.com, or your Bussmann series product sales representative, for assistance in selecting an appropriate fuse holder or block product for your application.

Kind regards,



AJ Johnson
Product Manager