

1 Products affected

Product hierarchy no. *	Part no.	SBU	Type / Description	Customer part no.
SBU PG PGU Type 02 007 060 0000002258	See list below	Strip Block	4758	

*SBU (2-digit) / PG (3-digit) / PGU (3-digit) / Type (10-digit)

List of part numbers affected							
4758.3000	4758.3200	4758.3400	4758.4000	4758.4200	4758.4400	4758.5000	4758.5200
4758.5400	4758.6000	4758.6200	4758.6400	4758.7000	4758.7200	4758.7400	4758.8000
4758.8200	4758.8400						


2 Type of change

Modification of approval marks.
 Slight modification on the lateral indentation.


3 Detailed description of change

New combined cURus approval mark instead of separate UR and CSA marks.
 Slight modification on the lateral indentation.


Old marking




New marking



Old form



New form



4758 Strip Block					0118.2242	
creation date	created by	release date	released by	notification no.	revision	page
2014-09-15	hotzar	2015-02-17	hotzar	27061	-	1 of 2

4 Reason of change

Consolidation of North American approval marks with the combined cURus mark.
 Slight modification on the lateral indentation because of optimization of the injection process.

5 Release date

The change will be rolled-out individually by all part numbers affected starting ww 12/2015 and last approx. 12 months.

6 Impact of change and recommended action

Form: Yes Socket has two slit on the both side
 Fit: No There are no dimensional changes
 Function: No No change on the specification
 Production Site: No There is no change of the production site
 Product Label: Yes CSA and UR replaced by cURus mark

7 Reference Documents / Attachments

Kind of document	Document number	Remarks
Data Sheet 4758		

4758 Strip Block					0118.2242	
creation date	created by	release date	released by	notification no.	revision	page
2014-09-15	hotzar	2015-02-17	hotzar	27061	-	2 of 2